District 1
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

## **Release Notification and Corrective Action**

				OF	PERATOR		Initial Repo	ort 🛛 Final Report	
Name of Co	mpany C	ConocoPhil	lips Com	pany	Contact Monica D. Johnson				
Address				ton, NM 87401	Telephone No. 505-599-3458				
Facility Name Lindrith B Unit #78					Facility Type Gas Well			(API # 30-039-25066)	
Surface Ow	ner <b>Fe</b>	deral		Mineral Owne	r Federal		Lease No	. NM SF-078907	
LOCATION OF RELEASE									
Unit Letter	Section	Township	Range	Feet from the N	Jorth/South Line	Feet from the	East/West Line	County	
<u>L</u>	6_	T24N	R2W	2030'	South	143'	West	Rio Arriba	
Latitude 36.33818° Longitude 107.09818°									
Type of Release – Condensate  NATURE OF RELEASE  Volume of Release – 15 BBL  Volume Recovered - 7 BBL									
					Volume of Release – 15 BBL Volume Recovered - 7  Date and Hour of Occurrence Date and Hour of Disco				
plugs			emovea a	ump valve	11/11/05 11/11			– 10:00 a.m.	
Was Immedia	ate Notice (		, $\square$		If YES, To Whom?				
			res 🔲 No	☐ Not Required	Denny Foust – OCD – via email				
By Whom?		Monios	Johnson		Mark Kelly – BLM – via email  Date and Hour – 11/21/05 – 1:30 p.m. via e-mail				
Was a Water	course Read		JUIIIISUII		If YES, Volume Impacting the Watercourse.				
, , as a mass	odinse med		Yes 🖾 🛚	No	in 125, voiding	in TES, volume impacting the watercourse.			
If a Watercourse was Impacted, Describe Fully.*									
Describe Cause of Problem and Remedial Action Taken.* Suspected vandal(s) removed the 2" plugs from the dump to the									
condensate tank, which resulted in a spill of 15 BBL condensate. The spilled fluids remained inside the secondary									
								spill affected the soils	
inside the	dike in a	n area 25'	x 15' x 8"	deep. The pum	iping unit was	shut in and t	he plugs repla	ced.	
ı									
Describe Area Affected and Cleanup Action Taken.* The spilled fluids remained inside the secondary containment dike, and									
								inside the dike in an	
								ils were excavated	
				r remediation, \					
			.,						
								ant to NMOCD rules and	
								ses which may endanger the operator of liability	
								surface water, human health	
				nce of a C-141 repor	t does not relieve	the operator of res	ponsibility for con	apliance with any other	
	or local la	ws and/or regu	ılations.		1				
Signature:	Mini	10 27-5	Johns	lM .		OIL CONSI	ERVATION D	IVISION TO THE REPORT OF THE PERSON OF THE P	
			1	<u> </u>	1		Den	y tour	
Printed Name	: M	onica D. Jo	hnson		Approved by D	istrict Supervisor:	for Cl	navlie Penny	
Title:	Env	vironmenta	l Analyst		Approval Date:	12/28/0	S Expiration Da	ate: 293031/15	
C mail Adda	www.manie	sa lohneen	ത്രാഹം	phillips.com	Conditions of A	/ / Innroval:		For Sol	
E-man Addre	SS. IIIOIIIC	.a.jumsun	(WCOIIOCO	primps.com		хрргочаг.		Attached Wife J	
Date: 1	1/21/05		Phone:	505-599-3458				S ON SCENE	
Attach Addit	tional She	ets If Necess	ary		14 10	^ -		R PROMETE	
					NUGH 6	2536220	6606	E ON DOWN	
								Manual de De	
								S S S S S S S S S S S S S S S S S S S	