

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report


Name of Company	Williams Midstream	Contact	Aaron Dailey
Address	188 County Road 4900	Telephone No.	(505) 632-4708
Facility Name	AXI Apache J003 Lateral	Facility Type	Pipeline
Surface Owner	Jicarilla Tribe	Mineral Owner	BLM
		Lease No.	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	7	25N	5W					Rio Arriba

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	Natural Gas	Volume of Release	: 120 MCF	Volume Recovered	: TBD
Source of Release	AXI Apache J 003 lateral	Date and Hour of Occurrence	4.22.10 @ 9:00 am	Date and Hour of Discovery	4.22.10 @ 12:00 pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required				
*Immediate notice to Tribe was given	Bryce Hammond, BLM Inspector/Jicarilla Oil and Gas Administration				
By Whom?	Bruce Armenta, Team Lead, Jicarilla Gathering	Date and Hour	4.22.10 @ 12:45 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				
				RCVD APR 28 '10	
If a Watercourse was Impacted, Describe Fully.*				OIL CONS. DIV.	
Describe Cause of Problem and Remedial Action Taken: Operator discovered lower than normal pressure on wells and visually inspected the pipeline until he traced out the source of the leak. Corrosion was the cause of the release. Operator blocked in the 5 wells on the lateral.					
Describe Area Affected and Cleanup Action Taken: Gas loss to atmosphere. No impact to soil or groundwater.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		<b>OIL CONSERVATION DIVISION</b>			
Printed Name: Aaron Dailey		Approved by District Supervisor:			
Title: Environmental Specialist		Approval Date:		Expiration Date:	
E-mail Address: aaron.dailey@williams.com		Conditions of Approval:			Attached <input type="checkbox"/>
Date: 4.26.10 Phone: (505) 632-4708					

\* Attach Additional Sheets If Necessary