

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

Aste o, New Mexico

July 30, 1949

Mr. John Ford, Superintendent
Gallup Dome, Inc.
Gallup, New Mexico

Dear Sir:

Enclosed you will find the necessary forms for your use in plugging and abandoning your Gallup Dome well. Also enclosed is Supplemental Circular No. 6-A which you will follow these instructions for the work to be done. As I explained to you, in order to get your bond cancelled, the well must be permanently abandoned. In that event, you will fill the hole to the top with well mixed heavy mud and cement a steel marker which will extend at least four feet above the ground.

For temporary abandonment you could install a swedge nipple or bull plug in the top of the casing, fill up the cellar to the surface so there will be no danger of anything falling in. If this is done, you understand, that your bond will not be cancelled until the well is permanently abandoned.

Yours very truly,

Al Greer

AG:mt

P.S. In the event that you decide to permanently abandon this well, due notice shall be given the Commission as to when plugging operations will begin.

C
O
P
Y

