

George Z. Ziegler

Mail to District Office, Oil Conservation Commission, to which Form O-101 was sent not later than twenty days after completion of well. Follow instructions in Guide and Regulations of the Commission. Submit in **QUINTUPLICATE**. *See Appendix for number of Copies*

ANDRO EIDAL CO.  
(CORPORATE OFFICE)

E 3213 - 10 Grace Hoxsey

Well No. 1 in NE ¼ of SW ¼ of Sec. 32, T. 16 N R. 6W S. 104M

## Wildcat

Pool.....McKinley

Well is 3300 feet from N line and 1980 feet from W line.

of Section 32 If State Land the Oil and Gas Lease No. is E 3213-1 0

Drilling Commenced.....**March 2 1956**....., 19..... Drilling was Completed.....**Mar 19 1956**....., 19.....

Name of Drilling Contractor..... **Bash Drilling Co**.....

Address Albuquerque N M

Elevation above sea level at Top of Tubing Head..... **6615**..... The information given is to be kept confidential until  
 ..... **NO** ..... 19.....

## OIL SANDS OR ZONES

**NOTE**

No. 1, from \_\_\_\_\_ to \_\_\_\_\_ No. 4, from \_\_\_\_\_ to \_\_\_\_\_

No. 2, from ..... to ..... No. 3, from ..... to .....

No. 3, from ..... to ..... No. 6, from ..... to .....

## IMPORTANT WATER SANDS

Include data on rate of water inflow and elevation to which water rose in hole.

No. 1, from 885 to 890 feet Artesian - fresh

No. 2. from 955 to 1001 See A rtistan- brackish

No. 3, from \_\_\_\_\_ to \_\_\_\_\_ feet.

No. 4, from ..... to ..... feet .....

### CASING RECORD

| SIZE | WEIGHT<br>PER FOOT           | NEW OR<br>USED | AMOUNT | KIND OF<br>SHOE | CUT AND<br>PULLED FROM | PERFORATIONS | PURPOSE |
|------|------------------------------|----------------|--------|-----------------|------------------------|--------------|---------|
| NONE | (Excep t Surface P lug - 51" |                |        |                 |                        |              |         |
|      |                              |                |        |                 |                        |              |         |
|      |                              |                |        |                 |                        |              |         |

## MUDDING AND CEMENTING RECORDS

| SIZE OF HOLE | SIZE OF CASING | WHERE SET | NO. BAGS OF CEMENT | METHOD USED          | MUD GRAVITY | AMOUNT OF CEMENT USED                          |
|--------------|----------------|-----------|--------------------|----------------------|-------------|------------------------------------------------|
| 4 3/4        |                |           | 40                 | Pumped around D Stem |             | 5 sks Aq uegel<br>1 Baroid on<br>top of Cement |


### RECORD OF PRODUCTION AND STIMULATION

(Record the Process used, No. of Qts. or Gals. used, interval treated or the)

**NONE**

### Result of Production Stimulation

## ..Depth Cleaned Out



If drill-stem or other special tests or deviation surveys were made, submit report on separate sheet and attach hereto

## PRODUCTION

Length of Time Shut in.....

## Northwestern New Mexico

## FORMATION RECORD

ATTACH SEPARATE SHEET IF ADDITIONAL SPACE IS NEEDED

.....  
{Date}

Position or Title.....**AGENT**.....

