

NO. OF COPIES RECEIVED	6
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	4

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</p>	
<p>1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole</p> <p>2. Name of Operator Walker Bros. Oil Co.</p> <p>3. Address of Operator P. O. Box 18715, Oklahoma City, Oklahoma</p> <p>4. Location of Well UNIT LETTER D 661 FEET FROM THE North LINE AND 672 FEET FROM THE West LINE, SECTION 26 TOWNSHIP 17N RANGE 8W NMPM.</p>	<p>7. Unit Agreement Name</p> <p>8. Farm or Lease Name Santa Fe</p> <p>9. Well No. 1</p> <p>10. Field and Pool, or Wildcat Wildcat</p> <p>15. Elevation (Show whether DF, RT, GR, etc.) 6942 Ground</p> <p>12. County McKinley</p>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged #1 Santa Fe as follows on May 6, 1965
100' plug - 23 sx-1825 to 1925
50' plug -14 sx -200 to 250
Heavy gel mud between plugs; above 200' flushed w/fresh water.
Cap on top with 4" iron marker alongside. location cleaned and
pits backed filled.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. E. Lanth TITLE Geologist DATE May 17, 1965

Original Signed Emery C. Arnold
APPROVED BY _____ TITLE Supervisor Dist. # 3 DATE JUN 8 1965

CONDITIONS OF APPROVAL, IF ANY:

