NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico



MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

instructions in the Rules and Regulation				ii. See additional
REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON RESULTED OF CASING SHUT-	LT OF TEST	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL	REPORT ON RECO	MPLETION	REPORT ON (Other)	
Following is a report on the work Great Western Drilling (Company or Open Great Western Drilling (Contractor	Company erator)	under the heading no	Santa Fe	Place)
(Contractor) T. 171 , R. 9W , NMPM , Wildcat				
33051 - 9-5/8" 8 rnd. w/325 sacks @ 5:30 A. After 36 hours, the ca was satisfactory, so d	M. July 18, 1955. sing was pressured w	0 and 36# J-59 /1000 pai for	casing was set @ 33	
			H	UG 111955 CON. COM. DIST. 3
Witnessed by	Great Weste	m Drilling Co	t the information given above is	
Oil conservation (Name) Oil and Gas Inspector Dist. #	COMMISSION (LING) (Date)	Name		rintendent Company

•				
* *	OIL CONSERVA	TION COMMISSION		
1		AZTEC DISTRICT OFFICE		
		No. Copies Received 3		
	DIST	DISTRIBUTION		
		NO. FURNISHED		
	 Operator			
• • •	Santa Fe			
	Proration Office			
	State Land Office			
	13. S. G. S.			
	Transporter			
	File			

 $\mathcal{Z} = \frac{1}{2} \left(\frac{1}{2} \right)^{\frac{1}{2}} = \frac{1}{2} \left(\frac{1}{2} \right)^{\frac{1}{2}}$