

X			

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 030677
Unit Star Lake

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

ILLEGIBLE

CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 25, 1963

Well No. Star Lake is located 330 ft. from N line and 330 ft. from E line of sec. 5

NW-NW-NW Section 5 18N 5W N117W
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
(Field) Maldenley New Mexico
(County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6368.6 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)


WORKING Plugging Data

Plug-1-9242 to 9130
Plug-2-8150 to 8050
Plug-3-6450 to 6350
Plug-4-5150 to 5050
Plug-5-3950 to 3850
Plug-6-2100 to 2000
Plug-7-0 to 35
470 sacks cement Halliburton

TOPS:

Mancoes 2050
Greenhorn 3843
Dakota 3592
Tudito 5095
Entrada 5193
Penn 8094
Miss 9145
Granite 9242

U. S. GEOLOGICAL SURVEY
WASHINGTON, D. C.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Star Lake Unit. M. F. Abraham

Address 424-1st National Bank Bldg. N. W.

Albuquerque, New Mexico

M. F. Abraham

By Oscar Abraham

Title Oscar Abraham