

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM-53365
2. NAME OF OPERATOR James L. Ludwick		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 70, Farmington, Nm 87499		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 330' FSL 330; FWL		8. FARM OR LEASE NAME Federal 8
14. PERMIT NO.		9. WELL NO. #4
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6601 GR		10. FIELD AND POOL, OR WILDCAT Paperswash <i>mv</i>
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 8, T19N, R5W
		12. COUNTY OR PARISH McKinley
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACURE TREAT	<input type="checkbox"/>	FRACURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		
PULL OR ALTER CASING	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
ABANDON*	<input checked="" type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Request to Plug & Abandon.

Plans for plugging well Fed. 4-8

Pull 3/4 " rods & 2 3/8" tubing.

Fill 5 1/2" casing with water, break down perms at 1945' to 1959'
two shots per ft.

Fill 5 1/2" casing with 140 sks of neat cement, 6% Gel.
Squeeze 5 sks. cement into perf's.

Install dry hole marker, back fill pits and reseed location.

Work to be completed on or before June 31, 1994.

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

18. I hereby certify that the foregoing is true and correct

SIGNED James L. Ludwick TITLE Operator

DATE 10/21/93

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

APPROVED

*See Instructions on Reverse Side

NM000

DISTRICT MANAGER

1. *Chlorophyll a*

2. *Chlorophyll b*

IN REPLY REFER TO:
(07337)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT
FARMINGTON DISTRICT OFFICE

1235 La Plata Highway
Farmington, New Mexico 87401

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: 4 Federal 8

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Leases."
2. **Mike Flaniken** with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
3. The following modifications to your plugging program are to be made (when applicable):

Note: The volume of cement used on the 5 1/2" production casing was not adequate to circulate to the surface.

At a minimum! (Place cement plugs thru the 2 3/8" tubing)

- 1.) *Spot a cement plug from 1985' (PBTD) to 1885' plus 50 linear feet excess. Tag TOC.*
- 2.) *Perforate @ 511', place a cement plug from 511' to 411' inside & outside the casing plus 100 ft excess.*

Office Hours: 7:45 a.m. to 4:30 p.m.

- 3.) *Perforate @ 87' and circulate cement to the surface.*