

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT ..." (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL GAS WELL OTHER

2. Name of Operator
James Hatcher *for Henry S. Birdseye*

3. Address of Operator
Bloomfield Oilfield Service Co. Box 1641 Bloomfield, N.M.

4. Location of Well
UNIT LETTER G 2310 FEET FROM THE N LINE AND 2310 FEET FROM THE E LINE, SECTION 10 TOWNSHIP 19N RANGE 10W NMPM.

7. Unit Agreement Name
Unknown

8. Farm or Lease Name
Henry S. Birdseye

9. Well No.
State # 2

10. Field and Pool, or Wildcat
Menefee

12. County
McKinnley

15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

| NOTICE OF INTENTION TO: | | SUBSEQUENT REPORT OF: | |
|--|--|---|--|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input checked="" type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input checked="" type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> | |
| | | OTHER _____ | |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-30-81- Moved rig and equipment to location and rig up
Picked up 3 7/8 bit and cleaned out to bottom, 594, mixed and pumped 15 sacks class A cement. Plug set from 594 to 470. Pulled tubing back to 150 and mixed and pumped 15 sacks class A cement. Plug set from 150 to 30, pulled tubing to 30 ft., mixed and pumped 10 sacks class A cement. Plug set from 30 ft. to surface.

10-1-81- Rig down and move rig and equipment back to yard in Bloomfield.

10-9-81- Cleaned location, leveled pits and install dry hole marker.

10-9-81- Location ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED James Hatcher TITLE _____ DATE 10-12-81

APPROVED BY Jeff A. Edmister TITLE Deputy Oil & Gas Inspector DATE 10-15-81

REVISIONS OR APPROVAL, IF ANY:

SANTA FE PAC RR 10 1

H 10 19N 10W

30-031-07031

2310/N 990/E

P





**ACS Business Process Solutions
Best and Final Offer**

Prepared for

**State of New Mexico
Oil Conservation Division**

May 7, 2002



People Making Technology Work™