

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Chaco Oil Company		8. Farm or Lease Name Santa Fe Pacific RR
3. Address of Operator P.O. Box 537, Farmington, New Mexico 87401		9. Well No. 21 (I-4)
4. Location of Well UNIT LETTER <u>B</u> <u>310</u> FEET FROM THE <u>North</u> LINE AND <u>2290</u> FEET FROM THE <u>East</u> LINE, SECTION <u>29</u> TOWNSHIP <u>20N</u> RANGE <u>9W</u> NMPM.		10. Field and Pool, or Wildcat Red Mountain MV
15. Elevation (Show whether DF, RT, GR, etc.) 6480 GR (Re-Surveyed)		12. County McKinley

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We propose to plug and abandon this well. We will clean out to TD of 467 feet and spot a 5 sx cement plug from bottom up which should give about 250' of cement fill. We will set a standard dry-hole marker with a 2 sx surface plug.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mark E. Weidner TITLE Agent DATE 5/31/79

Original Signed by A. R. Kendrick
APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: