G/11/97 Open well to atmosphere, slight blow at first. Shut in to see if pressure would build, no buildup. RUTS. Made 25 swab runs, total 10 bbls water, no oil, no gas. Shut well in. 6/12/97 Load and haul cement and equipment to location. Prepare well to plug. 6/ 13 & 14 /97 Plug #1 - 2323'-1558' with 59 sxs cement. Tagged with tubing after 4 hrs at 1558'. Press test to 500# - 15 mins OK. Plug #2 - 1298'-1110', run 18 sxs plug balanced 25% excess. Plug #3 - 540'-430' - run 8 sxs plug balanced. Plug #4 - Perfd 430', squeezed with 43 sxs, top plug inside at 300'. Plug #5 - Perfd 236', run 80 sxs, circulated to surface. Erected dry hole marker.	Distributio	n: O+4 (BLM); 1-Accounting; 1- Crystal; 1-File	
DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT Budget Stemus No. 1064-013 Experime Wheat 1,1993 Experime Management SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to despen or reentry to a different reservoir. If Human Antonio Per	Form 3160-5	UNITED STATES	FORM A DDD OVED
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or neentry to a different reservoir. Use "APPLICATION FOR PERMIT"—for such proposals SUBMIT IN TRIPLICATE 1. Type of Well One Cas. Merrino Oil & Gas Corporation Address und Forbagos No. 60 Reilly Avenue, Farmington, NM 87401-2634 (505) 327-9801 For Reilly Avenue, Farmington, NM 87401-2634 (505) 327-9801 The Company Printing Seat, Farmington, NM 87401-2634 (505) 327-9801 For Reilly Avenue, Farmington, NM 87401-2634 (505) 327-9801 The Company Printing Seat, Farmington, NM 87401-2634 (505) 327-9801 The Company Printing Seat, Farmington, NM 87401-2634 (505) 327-9801 The Company Printing Seat, Farmington, NM 87401-2634 (505) 327-9801 The Company Printing Seat, Farmington, NM 87401-2634 (505) 327-9801 The Company Printing Seat, Farmington, NM 87401-2634 (505) 327-9801 The Company Printing Seat, Farmington, NM 87401-2634 (505) 327-9801 The Company Printing Seat, Farmington, NM 87401-2634 (505) 327-9801 The Company Printing Seat, Farmington, NM 87401-2634 (505) 327-9801 The Company Printing Seat, Farmington, NM 87401-2634 (505) 327-9801 The Company Printing Seat, Farmington, NM 87401-2634 (505) 327-9801 The Company Printing Seat, Farmington, NM 87401-2634 (505) 327-9801 The Company Printing Seat, Farmington, NM 87401-2634 (505) 327-9801 The Company Printing Seat, Farmington, NM 87401-2634 (505) 327-9801 The Company Printing Seat, Farmington, NM 87401-2634 (505) 327-9801 The Company Printing Seat, Farmington, NM 87401-2634 (505) 327-9801 The Company Printing Seat, Farmington, NM 87401-2634	(June 1990)	DEPARTMENT OF THE INTERIOR	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill for to deapen or recently to a different reservoir. SUBMIT IN TRIPLICATE 1. If Uses or CA, Agreement Designation SUBMIT IN TRIPLICATE 2. Well Name and No. Mecrolin Oil & Gas Corporation Merrion Oil & Gas Corporation Address and Floropass No. 610 Relity Avenue, Farmington, NM 87401-2634 1. Leaston of Vide Coscap. Soc. 1, Am. of Survey Description 660' Isl & 660' Isl & 660' Isl (SESE) Section 12, T20N, R6W 12. CHECK APPROPRIATE BOX (s) TO INDICATE NATURE OF NOTICE, REPORT. OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of tenter Notice of tenter Notice of tenter Frank Abandonment Report JUN 3 0 1957 Recompletion Describe Proposed or completed Operation (Clearly state all portional death, and give pertinent distri, including estimated due of starting any proposed work. If well in disectionally strilled, give submirtude boundard and four vertical depths for all analous and zoose perturns in this work.) 6/11/97 Consume this office of the second point of the second point of the second work. If well it disectionally strilled, give submirtude boundard and four vertical depths for all analous and zoose perturns in this work.) 6/12/97 Load and haul cement and equipment to location. Proper well to plug. 6/13 & 14/97 Cleaned up location, closed pit. 10. Ibenety such as forced by a sea forced. The second plug days are forced. Exceeded with tubing after 4 hrs at 1558'. Press test to 500# - 15 mins OK. Plug #3 - 740-430'. run 8 sxs. plug balanced 25% excess. Plug #3 - 740-430'. run 8 sxs. plug balanced. Plug #4 - Perif 430', squeezed with 43 sxs, top plug inside at 300'. Plug #5 - Perif 236', run 80 sxs. circulated to surface. Erected dry hole marker. 6017/97 Cleaned up location, closed pit.			•
Do not use this form for proposals to drill or to deapen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals SUBMIT IN TRIPLICATE 1. Syne d'Well Of Gus Syne Well Congress			
Use "APPLICATION FOR PERMIT"—" for such proposals SUBMIT IN TRIPLICATE 7. If Use or CA. Agreenced Designation SUBMIT IN TRIPLICATE 7. If Use or CA. Agreenced Designation Case Ca	_		NM-7774
SUBMIT IN TRIPLICATE 1. Type of Well	Do not		6. If Indian, Allottee or Tribe Name
Type of Well		Use "APPLICATION FOR PERMIT" for such proposals	
On Gas Merrion Oil & Gas Corporation McCollum No. 1		SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation
Neman and No. New Column No. 1			
None of Operator Merrion Oil & Gas Corporation 3. Address and Telephone No. 610 Reilly Avenue, Farmington, NM 87401-2634 1. Location of Well (Footings, Sec., T., R. M., or Survey Description) CHECK APPROPRIATE BOX (s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION Price of ACTION Notice of Intent Note Construction Note Constr			
Mecrino Oil & Gas Corporation 3. Address and Telephone No. 610 Relial Venence, Farmington, NM 87401-2634 (505) 327-9801 4. Location of Well (Footage, Sec., T. R., M., or Survey Description) 660° fil & 660° fel (SESE) Section 12, T20N, R6W 12. CHECK APPROPRIATE BOX (s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION 13. Notice of Intent. 14. Notice of Intent. 15. Subsequent Reput. 15. July 3 0 1967 16. Plug fil a Subsequent Reput. 15. Describe Proposed or completed Operations (Clearly state all pertinon details, and give pertinont datas, including estimated data of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and two vertical depths for all materias and zones pertinent to this work.) 16. 11. Poper well to atmosphere, slight blow at first. Shut in to see if pressure would build, no buildup. RUTS. 17. Made 25 swab runs, total 10 bbls water, no oil, no gas. Shut well in. 18. Altering Casing. 19. Plug fil - 2323*-1558' with 59 sxs cement. Tagged with tubing after 4 hrs at 1558'. Press test to 500# - 15 mins OK. 19. Plug fil - 2323*-1558' with 59 sxs cement. Tagged with tubing after 4 hrs at 1558'. Press test to 500# - 15 mins OK. 19. Plug fil - 2326, run 80 sxs, circulated to surface. Erected dry hole marker. 10. First bour foregreen and control of the starting and correct startin			8. Well Name and No.
30-031-05436 10. Field and Pool, or Exploratory Area 11. Country or Parish, State 12. CHECK APPROPRIATE BOX (s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 177E OF SUBMISSION 177E OF SUBMISSION 177E OF SUBMISSION 177E OF ACTION 177E OF ACTION 177E OF ACTION 177E OF SUBMISSION 177E OF ACTION	4		
Location of Well (Pontage, Sec. T. R., M. of Survey Description) Location of Well (Pontage, Sec. T. R., M. of Survey Description) Franciscan Lake Mesaverd			
Locasion of Well (Footage, Sec. T. R. M., or Survey Description) Franciscan Lake Mesaverd	610 Re	illy Avenue, Farmington, NM 87401-2634 (505) 327-9801	
11. County or Parial, State McKinley County, New Mexico New Construction New Constru			
Section 12, T20N, R6W McKinley County, New Mexico CHECK APPROPRIATE BOX (s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Notice of Intent Subsequent Report Subsequent Report Non-Routine Fracturing Non-Routine Fracturing Water Shat-Off Casing Repair Casing Repair Casing Repair Other Conversion to Injection Dispose Water Other Speciment details, and give perfittent details, and give perfittent date, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perfitnent to this work.) Open well to atmosphere, slight blow at first. Shut in to see if pressure would build, no buildup. RUTS. Made 25 swab runs, total 10 bbls water, no oil, no gas. Shut well in. 6/11/97 Load and haul cement and equipment to location. Prepare well to plug. 6/13 & 14/97 Plug #1 - 2323'-1558' with 59 sxs cement. Tagged with tubing after 4 hrs at 1558'. Press test to 500# - 15 mins OK. Plug #2 - 1298'-1110', run 18 sxs plug balanced. Plug #3 - 540'-430' - run 8 sxs plug balanced. Plug #4 - Perfd 240', squeezed with 43 sxs, top plug inside at 300'. Plug #5 - Perfd 236', run 80 sxs, circulated to surface. Erected dry hole marker. 6/17/97 Cleaned up location, closed pit. 11. I hereby ceebs that the foreign runs and correct Signer Steven S. Dunn Title Drig & Prod Manager Date 6/23/97	660	' fsl & 660' fel (SESE)	
Type of Submission Type o	- A	·	
Notice of Intent	×		
Notice of Intent New Construction Notice of Intent New Construction New Construction New Construction Non-Routine Fracturing Recompletion Non-Routine Fracturing Non-Routine Fractu	12.	CHECK APPROPRIATE BOX (s) TO INDICATE NATURE OF NOTICE, REP	ORT, OR OTHER DATA
Recompletion New Construction New Construction Non-Routine Fracturing Non-Routine Fracturing Water Shut-Off Casing Repair Water Shut-Off Other Dispose Water Dispose Water		TYPE OF SUBMISSION TYPE OF ACTION	
Recompletion New Construction New Construction Non-Routine Fracturing Water Shut-Off Casing Repair Water Shut-Off Casing Repair Water Shut-Off Construction Dispose Water Water Shut-Off Casing Repair Water Shut-Off Construction of multiple completion to Injection Dispose Water Water Shut-Off Casing Conversion to Injection Dispose Water Water Shut-Off Casing Conversion to Injection Dispose Water Water Shut-Off Conversion to Injection Dispose Water Water Shut-Off Casing Conversion to Injection Dispose Water Water Shut-Off Casing Repair Water Shut-Off		Notice of Intent	Change of Plans
Subsequent Report JUN 3 0 1967 Plugging Back Non-Nontine Fracturing Water Shut-Off Casing Repair Water Shut-Off Conversion to Injection Dispose Water Shut-Off Conversion to Injection Dispose Water Shut-Off Conversion to Injection Dispose Water Shut-Off Conversion to Injection Dispose Water Shut-Off Conversion to Injection Dispose Water Shut-Off Conversion to Injection Dispose Water Special water		D) E U E D D E Recompletion	
Casing Repair Altering Casing Other Casing Repair Casing Repair Casing Repair Casing Repair Casing Repair Casing Conversion to Injection Dispose Water Proposed or completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Open well to atmosphere, slight blow at first. Shut in to see if pressure would build, no buildup. RUTS. Made 25 swab runs, total 10 bbls water, no oil, no gas. Shut well in. Open well to atmosphere, slight blow at first. Shut in to see if pressure would build, no buildup. RUTS. Made 25 swab runs, total 10 bbls water, no oil, no gas. Shut well in. Open well to atmosphere, slight blow at first. Shut in to see if pressure would build, no buildup. RUTS. Made 25 swab runs, total 10 bbls water, no oil, no gas. Shut well in. Open well to atmosphere, slight blow at first. Shut in to see if pressure would build, no buildup. RUTS. Made 25 swab runs, total 10 bbls water, no oil, no gas. Shut well in. Open well to atmosphere, slight blow at first. Shut in to see if pressure would build, no buildup. RUTS. Made 25 swab runs, total 10 bbls water, no oil, no gas. Shut well in. Open well to atmosphere, slight blow at first. Shut in to see if pressure would build, no buildup. RUTS. Made 25 swab runs, total 10 bbls water, no oil, no gas. Shut well in. Open well to atmosphere, slight blow at first. Shut in to see if pressure would build, no buildup. RUTS. Made 25 swab runs, total 10 bbls water, no oil, no gas. Shut well in. Open well to atmosphere, slight blow at first. Shut in to see if pressure would build, no buildup. RUTS. Made 25 swab runs, total 10 bbls water, no oil, no gas. Shut well in. Open well to atmosphere, slight blow at first. Shut in to see if pressure would build, no buildup. RUTS. Made 25 swab runs, tota		X Subsequent Report 111N 3 0 1907 Plugging Back	
Final Abandonme Graph Graph Other Other Dispose Water Other Dispose Water Other Ot			
Other Dispose Water (Poble Report results) consulted completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Open well to atmosphere, slight blow at first. Shut in to see if pressure would build, no buildup. RUTS. Made 25 swab runs, total 10 bbls water, no oil, no gas. Shut well in. 6/12/97 Load and haul cement and equipment to location. Prepare well to plug. 6/ 13 & 14 /97 Plug #1 - 2323'-1558' with 59 sxs cement. Tagged with tubing after 4 hrs at 1558'. Press test to 500# - 15 mins OK. Plug #2 - 1298'-1110', run 18 sxs plug balanced 25% excess. Plug #3 - 540'-430' - run 8 sxs plug balanced. Plug #4 - Perfd 430', squeezed with 43 sxs, top plug inside at 300'. Plug #5 - Perfd 236', run 80 sxs, circulated to surface. Erected dry hole marker. 6/17/97 Cleaned up location, closed pit. Title Drig & Prod Manager Date 6/23/97 Title Date 15 Date 1			
(Polis Report results of multiple completion on Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 6/11/97 Open well to atmosphere, slight blow at first. Shut in to see if pressure would build, no buildup. RUTS. Made 25 swab runs, total 10 bbls water, no oil, no gas. Shut well in. 6/12/97 Load and haul cement and equipment to location. Prepare well to plug. 6/13 & 14/97 Plug #1 - 2323'-1558' with 59 sxs cement. Tagged with tubing after 4 hrs at 1558'. Press test to 500# - 15 mins OK. Plug #2 - 1298'-1110', run 18 sxs plug balanced 25% excess. Plug #3 - 540'-430' - run 8 sxs plug balanced. Plug #4 - Perfd 430', squeezed with 43 sxs, top plug inside at 300'. Plug #5 - Perfd 236', run 80 sxs, circulated to surface. Erected dry hole marker. 6/17/97 Cleaned up location, closed pit. 14. Thereby certs that the foregonal is frue and correct Signed Steven S. Dunn Title Drlg & Prod Manager Date 6/23/97 Title Date Title 15. Date Title Date Title Title 16. Date Title Date Title Date Title 17. Date Title 18. Date Title Date Title 19.			
13. Describe Proposed or completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 6/11/97 Open well to atmosphere, slight blow at first. Shut in to see if pressure would build, no buildup. RUTS. Made 25 swab runs, total 10 bbls water, no oil, no gas. Shut well in. 6/12/97 Load and haul cement and equipment to location. Prepare well to plug. 6/13 & 14 /97 Plug #1 - 2323'-1558' with 59 sxs cement. Tagged with tubing after 4 hrs at 1558'. Press test to 500# - 15 mins OK. Plug #2 - 1298'-1110', run 18 sxs plug balanced 25% excess. Plug #3 - 540'-430' - run 8 sxs plug balanced. Plug #4 - Perfd 430', squeezed with 43 sxs, top plug inside at 300'. Plug #5 - Perfd 236', run 80 sxs, circulated to surface. Erected dry hole marker. 6/17/97 Cleaned up location, closed pit. 14. Thereby certify that the foregoing is free and correct Signed Steven S. Dunn Title Drlg & Prod Manager Date 6/23/97 Title Drlg & Prod Manager Date 6/23/97 JUN 2 > 1997 JUN 2 > 1997		190819 b	
Open well to atmosphere, slight blow at first. Shut in to see if pressure would build, no buildup. RUTS. Made 25 swab runs, total 10 bbls water, no oil, no gas. Shut well in. 6/12/97 Load and haul cement and equipment to location. Prepare well to plug. 6/13 & 14 /97 Plug #1 - 2323'-1558' with 59 sxs cement. Tagged with tubing after 4 hrs at 1558'. Press test to 500# - 15 mins OK. Plug #2 - 1298'-1110', run 18 sxs plug balanced 25% excess. Plug #3 - 540'-430' - run 8 sxs plug balanced. Plug #4 - Perfd 430', squeezed with 43 sxs, top plug inside at 300'. Plug #5 - Perfd 236', run 80 sxs, circulated to surface. Erected dry hole marker. 6/17/97 Cleaned up location, closed pit. 14. Thereby certly that the foregoint is frue and correct Signed Steven S. Dunn Title Drlg & Prod Manager Date 6/23/97 Title Date Title Date Title Date	13. Describe Pr	oposed or completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starts	Completion or Recompletion Report and Log form.)
Made 25 swab runs, total 10 bbls water, no oil, no gas. Shut well in. 6/12/97 Load and haul cement and equipment to location. Prepare well to plug. 6/ 13 & 14 /97 Plug #1 - 2323'-1558' with 59 sxs cement. Tagged with tubing after 4 hrs at 1558'. Press test to 500# - 15 mins OK. Plug #2 - 1298'-1110', run 18 sxs plug balanced 25% excess. Plug #3 - 540'-430' - run 8 sxs plug balanced. Plug #4 - Perfd 430', squeezed with 43 sxs, top plug inside at 300'. Plug #5 - Perfd 236', run 80 sxs, circulated to surface. Erected dry hole marker. 6/17/97 Cleaned up location, closed pit. 14. Thereby cerfly that the foregon is frue and correct Signed Steven S. Dunn Title Drlg & Prod Manager Date 6/23/97 Title Date Date Date Date Date Date Date Dat	give s	absurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*	ing any proposed work. It went is directionally diffied,
Plug #1 - 2323'-1558' with 59 sxs cement. Tagged with tubing after 4 hrs at 1558'. Press test to 500# - 15 mins OK. Plug #2 - 1298'-1110', run 18 sxs plug balanced 25% excess. Plug #3 - 540'-430' - run 8 sxs plug balanced. Plug #4 - Perfd 430', squeezed with 43 sxs, top plug inside at 300'. Plug #5 - Perfd 236', run 80 sxs, circulated to surface. Erected dry hole marker. 6/17/97 Cleaned up location, closed pit. 14. Thereby certify that the foregoint is rue and correct Signed Steven S. Dunn Title Drlg & Prod Manager Date 6/23/97 (This pace for Federal or State office yet) Species. Approved By Title	6/11/97	Open well to atmosphere, slight blow at first. Shut in to see if pressure would build, a Made 25 swab runs, total 10 bbls water, no oil, no gas. Shut well in.	no buildup. RUTS.
Plug #1 - 2323'-1558' with 59 sxs cement. Tagged with tubing after 4 hrs at 1558'. Press test to 500# - 15 mins OK. Plug #2 - 1298'-1110', run 18 sxs plug balanced 25% excess. Plug #3 - 540'-430' - run 8 sxs plug balanced. Plug #4 - Perfd 430', squeezed with 43 sxs, top plug inside at 300'. Plug #5 - Perfd 236', run 80 sxs, circulated to surface. Erected dry hole marker. 6/17/97 Cleaned up location, closed pit. 14. Thereby certify that the foregoint is rue and correct Signed Steven S. Dunn Title Drlg & Prod Manager Date 6/23/97 (This pace for Federal or State office yet) Species. Approved By Title	6/12/97	Load and haul cement and equipment to location. Prepare well to plug	
Plug #1 - 2323'-1558' with 59 sxs cement. Tagged with tubing after 4 hrs at 1558'. Press test to 500# - 15 mins OK. Plug #2 - 1298'-1110', run 18 sxs plug balanced 25% excess. Plug #3 - 540'-430' - run 8 sxs plug balanced. Plug #4 - Perfd 430', squeezed with 43 sxs, top plug inside at 300'. Plug #5 - Perfd 236', run 80 sxs, circulated to surface. Erected dry hole marker. 6/17/97 Cleaned up location, closed pit. 14. Thereby certify that the foregoing is rue and correct Signed Steven S. Dunn Title Drig & Prod Manager Date 6/23/97 Title Date Date Date 10. 2 5 1997		1 P	
Plug #2 - 1298'-1110', run 18 sxs plug balanced 25% excess. Plug #3 - 540'-430' - run 8 sxs plug balanced. Plug #4 - Perfd 430', squeezed with 43 sxs, top plug inside at 300'. Plug #5 - Perfd 236', run 80 sxs, circulated to surface. Erected dry hole marker. 6/17/97 Cleaned up location, closed pit. 14. Thereby certify that the foregoing is frue and correct Signed Steven S. Dunn Title Drlg & Prod Manager Date 6/23/97 (This pace for Federal of State office 12) Species. Approved By Title	6/ 13 & 14 /9		
Plug #3 - 540'-430' - run 8 sxs plug balanced. Plug #4 - Perfd 430', squeezed with 43 sxs, top plug inside at 300'. Plug #5 - Perfd 236', run 80 sxs, circulated to surface. Erected dry hole marker. 6/17/97 Cleaned up location, closed pit. 14. Thereby certify that the foregoing is frue and correct Signed Steven S. Dunn Title Drlg & Prod Manager Date 6/23/97 (This space for Federal or State office 18.) Approved By Title Date		Plug #1 - 2323'-1558' with 59 sxs cement. Tagged with tubing after 4 hrs at 1558'. P	ress test to 500# - 15 mins OK.
Plug #4 - Perfd 430', squeezed with 43 sxs, top plug inside at 300'. Plug #5 - Perfd 236', run 80 sxs, circulated to surface. Erected dry hole marker. 6/17/97 Cleaned up location, closed pit. 14. I hereby certify that the foregoing is frue and correct Signed Steven S. Dunn Title Drlg & Prod Manager Date 6/23/97 (This pace for Federal or State offic we) Species. Approved By Title Date			en e
Plug #5 - Perfd 236', run 80 sxs, circulated to surface. Erected dry hole marker. 6/17/97 Cleaned up location, closed pit. 14. Thereby certify that the foregoing is frue and correct Signed Steven S. Dunn Title Drlg & Prod Manager Date 6/23/97 (This space for Federal or State office W.) Species Approved By Title Date			
Cleaned up location, closed pit. 14. I hereby certify that the foregoing is frue and correct Signed Steven S. Dunn Title Drlg & Prod Manager Date 6/23/97 (This space for Federal or State office we) Species Approved By Title Date			••• • • • • • • • • • • • • • • • • •
14. I hereby certify that the foregoing is frue and correct Signed Steven S. Dunn Title Drlg & Prod Manager Date 6/23/97 (This space for Federal or State office we) Species. Approved By Title Date			
14. I hereby certify that the foregoing is frue and correct Signed Steven S. Dunn Title Drlg & Prod Manager Date 6/23/97 (This space for Federal or State office we) Species Approved By Title Date	6/17/97	Cleaned up location, closed pit.	
14. I hereby certify that the foregoing is frue and correct Signed Steven S. Dunn Title Drlg & Prod Manager Date 6/23/97 (This space for Federal or State office we) Species Approved By Title Date			
Signed Steven S. Dunn Title Drlg & Prod Manager Date 6/23/97 (This space for Federal or State office W.) Species: Approved By Title Date		Λ	
Signed Steven S. Dunn Title Drlg & Prod Manager Date 6/23/97 (This space for Federal or State office W.) Species: Approved By Title Date	14. I hereby cer	fify that the foregoing is true and correct	
(This space for Federal or State offic We) Species JUN 2 5 1997 Approved By Title Date	Signed	Steven S. Dunn Title Drlg & Prod Manager	
Approved By Title Date	(This space		
	Approved E	Title	JUN 2 3 1991
	Conditions		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.