

NO. OF COPIES RECEIVED		
DISTRIBUTION	3	
SANTA FE	1	
FILE	1	✓
U.S.G.S.		
LAND OFFICE		
OPERATOR	1	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
<b>K-4827</b>

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Corehole</b>	7. Unit Agreement Name
2. Name of Operator <b>Hoover H. Wright</b>	8. Farm or Lease Name <b>H. H. Wright</b>
3. Address of Operator <b>P. O. Box 2288, Santa Fe, New Mexico</b>	9. Well No. <b>2</b>
4. Location of Well UNIT LETTER _____, <b>640</b> FEET FROM THE <b>south</b> LINE AND <b>1470</b> FEET FROM THE <b>east</b> LINE, SECTION <b>32</b> TOWNSHIP <b>17N</b> RANGE <b>15W</b> NMPM.	10. Field and Pool, or Wildcat <b>Pinedale</b>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <b>McKinley</b>

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spud 5-11-65. Drilled 5" hole to 660' (TD). Ran electrical and Gamma Ray logs. With open end drill pipe placed 20 sacks cement at 660'-477', 15 sacks cement at 180'-40 and one sack at surface and installed 4" pipe marker. Abandon 5-14-65.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Harold Wright TITLE ~~XXXXXXXXXX~~ DATE 5-18-65

APPROVED BY Original Signed by Emery C. Arnold TITLE SUPERVISOR DIST. #3 DATE MAY 18 1966

CONDITIONS OF APPROVAL, IF ANY: