2. Name of Operator  Skelly 0:1 Company  3. Address of Operator  Box 730, Hobbs, New Max	NEW MEXICO OIL CONSERVATION  Y NOTICES AND REPORTS ON WELLS POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFF ON FOR PERMIT _** (FORM C-101) FOR SUCH PROPOSALS.  OTHER-	5a. Indicate Type of Lease State
4. Location of Well UNIT LETTER	1980 FEET FROM THE SOUTH LINE AND	1980  FEET FROM  10. Field and Pool, or Wildcat  Hospah - Gallup
THE West LINE, SECTION	6 · 17w	9-WNMPM.
	15. Elevation (Show whether DF, RT, GR, 6882 at	12. County McKinley
Check A	Appropriate Box To Indicate Nature of N	Notice, Report or Other Data SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER	<u></u>	DRILLING OPNS. PLUG AND ABANDONMENT
Well plugged and a  1. Spotted 30- 2. Spotted 30- 3. Spotted 10- pipe as dry 4. All interva	abandoned in following manner:  sack cement plug from 1578 to sack cement plug from 440 to 3 sack cement cap in top of 7-5/8 hole marker.  Ils not cemented were filled with and abandoned January 12, 196	310' (Point Lockout). 8"OB casing and installed 4" th heavy mud-laden fluid.
	above is true and complete to the best of my knowleds	
APPROVED BY MULLI CONDITIONS OF APPROVAL, IF ANY:	wlof TITLE Sup Pin	