

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	1
FILE	✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Burwinkle, Scanlon & Husky Energy, Inc.		8. Farm or Lease Name Santa Fe R.R.
3. Address of Operator Box 388 Aztec, New Mexico 87410		9. Well No. 2
4. Location of Well UNIT LETTER N , 165 FEET FROM THE South LINE AND 2145 FEET FROM THE West LINE, SECTION 21 TOWNSHIP 20N RANGE 9W NMPM.		10. Field and Pool, or Wildcat Chaco Wash MV
15. Elevation (Show whether DF, RT, GR, etc.)		12. County McKinley

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well plugged and abandoned as follows:

Set 15 sack plug from 563 feet to 500 feet.
Filled hole with drilling mud. Placed 5 sacks
cement at surface. Set surface marker.
Cleaned and leveled location.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
BURWINKLE, SCANLON & HUSKY ENERGY INC.			
SIGNED <u>Noel Reynolds</u>	TITLE <u>Agent</u>	DATE <u>April 3, 1972</u>	
Original Signed by A. R. Kendrick		TITLE <u>PETROLEUM ENGINEER DIST. NO. 3</u> DATE <u>APR 3 1972</u>	
APPROVED BY _____			
CONDITIONS OF APPROVAL, IF ANY:			