

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

RECEIVED
BLM

Lease Designation and Serial No.
NM-12335

6. If Indian, Allottee or Tribe Name

92 OCT -2 AM 11:36

SUBMIT IN TRIPLICATE

019 FARMING

Unit M.C.A. Agreement Designation

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Citation Oil & Gas Corp.

713-469-9664

3. Address and Telephone No.

8223 Willow Place South Ste 250 Houston, Texas 77070

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1820' FNL & 1700' FWL Sec 12, 17N, 9W

8. Well Name and No.

South Hospah Unit #34

9. API Well No.

10. Field and Pool, or Exploratory Area

S. Hospah Upper Sand

11. County or Parish, State

McKinley County, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other Plug and abandon

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Citation Oil & Gas Corp. request permission to plug and abandon this well by using the following procedure:

- 1) TIH w/open-end 2 7/8" tbg to TD (1661'). Spot 43 sx Class "B" cmt w/2% CaCl₂, pull to ±1200', circulate tbg clean. WOC 2 hrs.
- 2) Tag TOC, spot 9 ppg mud from TOC to ±610' TOH.
- 3) TIH w/pkr & tbg, set pkr at ±250'. Perforate 4 sqz holes at 610'. Pump 40⁸³ sx Class "B" cmt w/2% CaCl₂. Displace cmt w/9 ppg mud to ±525'. Reverse circ until clean, reset pkr, WOC 2 hrs.
- 4) Perf 4 sqz holes at 300'. Pump 32 sx Class "B" cmt w/2% CaCl₂. Displace cmt w/9 ppg mud to btm of pkr. Move pkr uphole 1 jt, reverse circulate w/mud until clean. LD tbg & pkr. WOC 2 hrs.
- 5) Perforate 4 sqz holes @ 120'. Pump 70 sx Class "B" cmt via csg to fill 7" csg & its annulus. Top off csg and annulus as necessary.
- 6) Cut off csg and weld on plate w/ 4" X 4' marker post.
- 7) Clean location.

14. I hereby certify that the foregoing is true and correct

Signed Sharon Ward

Title Production Regulatory Supv

Date 9-29-92

(This space for Federal or State office use)

Approved by _____

Title _____

Conditions of approval, if any:

APPROVED
AS AMENDED

OCT 06 1992

AREA MANAGER

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side