

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Burwinkle, Scanlon &amp; Husky Energy Inc.</b>	8. Farm or Lease Name <b>Santa Fe R.R.</b>
3. Address of Operator <b>Box 388, Aztec, New Mexico</b>	9. Well No. <b>3</b>
4. Location of Well UNIT LETTER <b>N</b> <b>165</b> FEET FROM THE <b>South</b> LINE AND <b>1815</b> FEET FROM THE <b>West</b> LINE, SECTION <b>21</b> TOWNSHIP <b>20N</b> RANGE <b>9W</b> NMPM.	10. Field and Pool, or Wildcat <b>Chaco Wash MV</b>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <b>McKinley</b>

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well plugged and abandoned as follows:

Set 15 sack plug from 539 feet to 480 feet.  
Filled hole with drilling mud. Placed  
5 sacks cement at surface. Set surface  
marker. Cleaned and leveled location.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

**BURWINKLE, SCANLON & HUSKY ENERGY INC.**

SIGNED *Paul Reynolds* TITLE Agent DATE April 3, 1972

Original Signed by **A. R. Kendrick**

APPROVED BY \_\_\_\_\_ TITLE PETROLEUM ENGINEER LIST NO. 3 DATE APR 3 1972

CONDITIONS OF APPROVAL, IF ANY: