Form 9-331 (May 1963)

## UNITED STATES SUBMIT IN TRIPLICATE (Other instructions on re-

Form approved. Budget Bureau No. 42-8014	
5. LEASE DESIGNATION AND SPRIAL N	<b>5</b> .
NM-081208	

MENI OF I	HE MILKION KING
GEOLOGICAL	SURVEY

SUNDRY	NOTICES	AND	<b>REPORTS</b>	ON	WELLS
SOLADIVI	11011025	d-III or to	deepen or plus	back to	a different

				~			
6.	IF	INDIAN,	ALLOTT	1	OH	TRIBE	NAME
_							
		•					
					- 7.		
₹,		. فد	•				
	-	-			. 1		

16. Check A	ppropriate Box To Indicate Nature of Notice, Report, c	or Other Data
14. PERMIT NO.	16. ELEVATIONS (Show whether DF, RT, GR, etc.) 7060 GR	Mekinley New Mex
	Unit D	Sec. 12, TIZN, R9W
At surface 1280'	FNL and 1280' FWL	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
4. LOCATION OF WELL (Report location of See also space 17 below.)	learly and in accordance with any State requirements.	South Hospak Dual
3. ADDRESS OF OPERATOR 1860 Lincoln St., Sui	te 1200, Denver, Colorado 80295	10. FIELD AND POOL, OR WILDCAT
Tenneco Oil Company		9. WELL NO.
2. NAME OF OPERATOR		8. FARM OR LEASE NAME
OIL GAS OTHER		South Hospah Unit
	nals to drill or to deepen or plug back to a different reservoir. TION FOR PERMIT—" for such proposals.)	7. UNIT AGREEMENT NAME

Check Appropriate Box To Indicate Nature of Notice, Report, o BUBSEQUENT BEPORT OF


NOT	ICE OF INTENTION TO:		1	<u> </u>	· · · · · · · · · · · · · · · · · · ·	_
	CONTRACTOR CARLYO		WATER SHUT-OFF		BEPAIRING WELL	i
TEST WATER SHUT-OFF	PULL OR ALTER CASING		FRACTURE TREATMENT		ALTERING CASING	i
PRACTURE TREAT	MULTIPLE COMPLETE				ABANDONMENT**	
SHOOT OR ACIDIZE	ABANDON*		SHOOTING OR ACIDIZING		***************************************	
	CHANGE PLANS		(Other)			-
REPAIR WELL	_ ,	V	(Nore: Report res Completion or Rec	sults of multiple completion Repor	completion on Well t and Log form.)	
Tomr	oorary Plug Back	1 / 1	Completion of rece			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.).

We propose to temporarily abandon the Lower Sand zone on this well as follows:

- MIRUPU. Pull and lay down both strings of tubing and rods. 1.
- Set WL BP at +1626.
- Run submersible pump on 2-7/8" EUE tubing to  $\pm 1600$ .
- Put on production and test.

Clean location of all debris.



18. I hereby certify that the foregoing is true and correct	TITLE	Div. Production Manager
(This space for Federal or State office use)		
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	The state of the s