

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
NM-081208

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME
South Hospah Unit

8. FARM OR LEASE NAME

9. WELL NO.
37X

10. FIELD AND POOL, OR WILDCAT
South Hospah Dual

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 12, T12N, R9W

12. COUNTY OR PARISH
McKinley

13. STATE
New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Tenneco Oil Company

3. ADDRESS OF OPERATOR
1860 Lincoln St., Suite 1200, Denver, Colorado 80295

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1280' FNL and 1280' FWL
Unit D

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
7060' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	


(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We propose to temporarily abandon the Lower Sand zone on this well as follows:

1. MIRUPU. Pull and lay down both strings of tubing and rods.
2. Set WL BP at +1626.
3. Run submersible pump on 2-7/8" EUE tubing to +1600.
4. Put on production and test.
5. Clean location of all debris.

SEP 16 1977



18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE Div. Production Manager

DATE 9/13/77

(This space for Federal or State office use)

APPROVED

TITLE

DATE

1977
E. I. McGRATH
DISTRICT ENGINEER

*See Instructions on Reverse Side