

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SAN ANTONIO	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- Water Injection		7. Unit Agreement Name
2. Name of Operator Tesoro Petroleum Corporation		8. Farm or Lease Name Santa Fe R.R.
3. Address of Operator 8520 Crownhill Boulevard, San Antonio, Texas 78209		9. Well No. 22
4. Location of Well UNIT LETTER <u>D</u> <u>1200</u> FEET FROM THE <u>North</u> LINE AND <u>65</u> FEET FROM THE <u>West</u> LINE, SECTION <u>7</u> TOWNSHIP <u>17N</u> RANGE <u>8W</u> NMPM.		10. Field and Pool, or Wildcat South Hospah-Upper Sand
15. Elevation (Show whether DF, RT, GR, etc.) 6937' GL 6949' RKB		12. County McKinley

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>


SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Completion

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-10-70: Ran Dresser-Atlas Strip Log and perforated the following intervals:
1533-36' RKB; 1544-47' RKB; 1552-55' RKB; 1559-63' RKB, 4 shots per foot.

7-2-70: Acid washed perforations with 300 gals. 15% NE acid. Minimum pressure
200 psi; maximum pressure 800 psi. Ran tubing; Baker-Lok-Set packer at
1500' RKB. Swabbed well down for completion as injection well.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>R. H. Schuman</u>	TITLE <u>Petroleum Engineer</u>	DATE <u>July 29, 1970</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR DIST. #3</u>	DATE <u>AUG 3 1970</u>
CONDITIONS OF APPROVAL, IF ANY:		