

August 3, 1982

## CERTIFIED MAIL

Tesoro Petroleum Corporation 2000 First of Denver Plaza Denver, Colorado 80202

## Gentlemen:

Reference is made to your Water Injection well No. 19 Hanson, NEwSWitsec. 6, T. 17 N., R. 8 W., McKinley County, New Mexico, Federal lease No. New Mexico 052931. Our records show that there are tight or damaged perforations above the packer, which have not been squeezed. It is doubtful that any significant benefits would be derived by breaking down these perforations and re-plugging them with cement.

You are hereby required to check the fluid level and/or pressure in the annulus monthly. This office will require a report of your first measurements. A record of subsequent measurements is to be available to the Minerals Management Service upon request and any significant changes are to be reported to this office as soon as practical after detection.

Failure to supply a report of your first measurements to this office, within 30 days of the date of this letter will result in an assessment of liquidated damages pursuant to 30 CFR 221. 54.

Sincerely yours,

Sue E. Umshler for James F. Sims District Oil and Gas Supervisor

cc: NMOCD



<u>-</u>

## 

The second section of the second section of the second second second section of the second se

ు కార్యాలు మండుకు కార్యాలు కార్య అంది మండుకు కార్యాలు క

ార్ ఈ మారు ఎంది ఎక్కుంటిం ఉన్నారు. కోర్యక్ష్మ్ ఎంది ఎక్కువు అధిక కాటక్ష్మ్ కార్ కోంట్ ఉన్న కార్పు ఎక్కువు ఎక్కు ఈ కాటక్ష్మ్ కార్పు కాట్లు కాటక్ష్మ్మ్ కాట్లు కాట్లు కాట్లు కాట్లు కాట్లు ప్రాణ్యంతో కాట్లు ఉన్న పోష్ట్ పోత్రంలో అనికి అన్నారు. పోష్ట్ కాట్లు ప్రమాద మంది కాట్లు కూడి పోష్ట్ కాట్లు కూడి కాట్లు పోష్ట్ ప్రమాది ఈ మార్క్ కాట్లు కూడి పట్టికి ఉంటే కూడి ప్రమాద మంది కాట్లు కూడి పోష్ట్ కాట్లు కూడికి కాట్లు పోష్ట్ కాట్లు కూడికి

and and the second of the seco

 $(\mathbb{R}^{n+1}(\mathbb{R}^n)_{n+1})_{n+1} = \mathbb{Q}_{n+1} \times \mathbb{Q}_{n+1} \times \mathbb{Q}_{n+1} \times \mathbb{Q}_{n+1}$ 

Line of the control of the second of the control of