Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

NM 052931 SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE 1. Type of Well 8. Well Name and No. Oil Gas Well Well HANSON FED. 20 2. Name of Operator 9. API Well No. BC & D OIL AND GAS CORP. 30-031-20158 3. Address and Telephone No. 10. Field and Pool, or Exploratory Area (505) 397-3972 P.O. Box 1680, Hobbs, NM 88241 South Hospah Upper Sand 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State McKinley, NM N, 5' FSL, 2635' FWL, Sec. 6, T17N, R8W CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Change of Plans Notice of Intent Recompletion **New Construction** Non-Routine Fracturing Plugging Back Subsequent Report Casing Repair Conversion to Injection Altering Casing X Final Abandonment Notice Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form) 13. Describe Proposed or Completed Operations (Clearly state all pertunent details, and give pertunent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertunent to this work.)* Please see attachment for P & A procedures. Date 09/20/01 President (This space for Federal or State office use) ACCEPTED FOR RECORD

Title 18 U.S.C. Section 1991, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, according to Diffusion statements or representations at to any matter within its jurisdiction.

HANSON WELL NO. 20 30-031-20158 SEC.6,T17N,R8W

6/01/01

MIRU PLUGGING EQUIPMENT, CONDUCT SAFETY MEETING, RLS. PKR, POOH AND LAY DOWN 2 3/8" TBG. AND PKR., PU AND TIH WITH 3.750" BIT, SCRAPER AND 2 7/8" TBG., TAG TD @ 1573', LOAD HOLE WITH WATER AND CIRCULATE CLEAN, SECURE WELL, SHUT IN.

6/4/01

CREW TO LOCATION, CONDUCT SAFETY MEETING, MIX 68 SXS. CLASS "B" NEAT CMT., ESTABLISH CIRCULATION AND PUMP 68 SXS. CMT. (80 CUBIC FEET) FLUSH WITH 3 BBLS. WATER, POOH WITH TBG., SECURE WELL, SI WOC.

6/05/01

CREW TO LOCATION, CONDUCT SAFETY MEETING, TIH WITH TBG. TAG TOC @ 1010', MIX 35 SXS. CLASS "B" NEAT CMT., ESTABLISH CIRCULATION AND PUMP 35 SXS. CMT. (41 CUBIC FEET) FLUSH WITH 3 BBLS. WATER., POOH WITH TBG. TO 700', ESTABLISH CIRCULATION AND CIRCULATE HOLE CLEAN, POOH WITH TBG., SECURE WELL, SI, WOC

6/06/01

CREW TO LOCATION, CONDUCT SAFETY MEETING, TIH WITH TBG., TAG TOC @ 730', POOH AND LAY DOWN TBG., PREPARE TO FREEPOINT CSG., CUT CSG. @ 612, POOH AND LAY DOWN CSG., SECURE WELL, SHUT DOWN DUE TO RIG REPAIRS.

6/08/01

CREW TO LOCATION, CONDUCT SAFETY MEETING, TIH WITH TBG., ROTATE TBG. INTO CSG. @ 612', CONTINUE TIH TO TAG TOC INSIDE CSG. @ 730', MIX 147 SXS. CLASS "B" NEAT CMT., ESTABLISH CIRCULATION TO PIT, PUMP 147 SXS. CMT (173 CUBIC FEET) WITH GOOD SLURRY TO PIT, POOH AND LAY DOWN TBG., TOP OFF SURFACE CSG. WITH CMT., HOLE STABLE, SHUT DOWN OVER NITE.

6/09/01

CREW TO LOCATION, OBSERVE SURFACE CSG. TO BE FULL OF CMT., RIG DOWN, MOVE ALL PLUGGING EQUIPMENT, INSTALL P&A MARKER CLEAN LOCATION, WELL PLUGGED.