

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65  
30-031-20182

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Dual (Oil &amp; Gas)</b>	5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator <b>Tenneco Oil Company</b>	5. State Oil & Gas Lease No.
3. Address of Operator <b>Suite 1200 Lincoln Tower Bldg. - Denver, Colo.</b>	7. Unit Agreement Name <b>Lone Pine Dakota "D" Unit</b>
4. Location of Well UNIT LETTER <b>F</b> <b>2180</b> FEET FROM THE <b>North</b> LINE AND <b>2180</b> FEET FROM THE <b>West</b> LINE, SECTION <b>13</b> TOWNSHIP <b>17</b> RANGE <b>9</b> NMPM.	8. Farm or Lease Name
	9. Well No. <b>13</b>
	10. Field and Pool, or Wildcat <b>Dakota</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>6994' GR</b>	12. County <b>McKinley</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <b>Convert to Dual</b> <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Move in completion unit, pull tubing, set CIBP @  $\pm$  2650', perforate "A" zone 2563'-72' w/2 JSPF, frac formation, swab, remove plug, install packer @  $\pm$  2650', run tubing. Produce "D" zone through tubing and "A" zone through annulus.

Reference NMOCC Order No. R-4341



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W L Shaver TITLE Sr. Production Clerk DATE 7/7/72

Original Signed by Emery C. Arnold

TITLE SUPERVISOR DIST. #3

DATE JUL 24 1972

CONDITIONS OF APPROVAL, IF ANY: