

NO. COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole		7. Unit Agreement Name
2. Name of Operator Tesoro Petroleum Corporation		8. Farm or Lease Name Santa Fe R.R.
3. Address of Operator 8520 Crownhill, San Antonio, Texas 78209		9. Well No. 28
4. Location of Well UNIT LETTER <u>H</u> <u>2160</u> FEET FROM THE <u>North</u> LINE AND <u>380</u> FEET FROM THE <u>East</u> LINE, SECTION <u>7</u> TOWNSHIP <u>17N</u> RANGE <u>8W</u> NMPM.		10. Field and Pool, or Wildcat Lone Pine - Dakota "D"
15. Elevation (Show whether DF, RT, GR, etc.) 6958' GL RKB 6969'		12. County McKinley

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set 69-sack plug TD (2835') back to 2580' (Entire Dakota).  
Set 80-sack plug 1950' back to 1640' (Hospah and Lower Hospah).  
Set 26-sack plug 780' back to 680' (Seven Lakes).  
Set 14-sack plug in top.  
9.1# mud left in hole between plugs; no pipe removed. Location cleared and ready for inspection.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. H. Newman TITLE Manager of Prod. Engineering DATE June 8, 1971  
APPROVED BY Ernest C. Cline TITLE Sup. Dist. III DATE 6-23-72  
CONDITIONS OF APPROVAL, IF ANY:

NEW MEXICO OIL CONSERVATION COMMISSION  
1000 RIO BRAZOS ROAD  
Aztec, New Mexico

Tesoro Pet. Corp.  
~~San Antonio~~  
San Antonio

RE: Plugging Reports

Gentlemen:

Form C-103, Notice of Intention to Plug, your Santa Fe RR 28 N-7-17N-8W  
Lease Well No. Unit- S-T-R  
was approved on 6-11-71. Your subsequent notice of plugging cannot be  
approved until a commission representative has made an inspection of the location  
to see:

- (1) all pits have been filled and leveled;
- (2) a steel marker, 4" in diameter and approximately 4' above mean ground level, must be set in concrete, this marker must have the quarter-quarter section or unit designation, section, township and range numbers, which shall be permanently stenciled or welded on the marker;
- (3) the location shall be cleared and cleaned of all junk;
- (4) the dead man wires must be cut.

The above are the minimum requirements.

Please notify us by filling in the blank form below when this work has been done so that our representative will not have to make more than one trip to the location.

on SL & set. 11/1/71

OIL CONSERVATION COMMISSION

By Emory L. Cline

Fill in below and return:

Lease Well No. Unit-S-T-R

is ready for your inspection and approval.

Operator

Name and title

Location OK  
6-7-3-72