

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-031-20207
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name LONE PINE DAKOTA "D"
8. Well No. 3
9. Pool name or Wildcat LONE PINE DAKOTA "D"
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 6987

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator BC & D OPERATING, INC.
3. Address of Operator P.O. BOX 1680, HOBBS, NM 88241
4. Well Location Unit Letter <u>J</u> : <u>2980</u> Feet From The <u>WEST</u> Line and <u>1710</u> Feet From The <u>SOUTH</u> Line Section <u>7</u> Township <u>17N</u> Range <u>8W</u> NMPM <u>MCKINLEY</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 6987

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PLEASE SEE ATTACHMENT

P & A WITNESSED BY MR. BRUCE MARTIN WITH NMOCD

11/3/00

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Donnie Hill TITLE PRESIDENT DATE 12/29/00

TYPE OR PRINT NAME DONNIE HILL TELEPHONE NO. (505) 397-3972

(This space for State Use)

APPROVED BY H. Villanueva TITLE DEPUTY OIL & GAS INSPECTOR, DIST. 3 DATE FEB - 5 2001

CONDITIONS OF APPROVAL, IF ANY:

LONE PINE DAKOTA #3
SEC. 7, T17N, R8W
MCKINLEY, NM

- 10/30/2000 MIRU P&A equipment, conduct safety meeting, PU and TIH w/ 2 7/8" tbg. to tag @ 2795', secure well, SDFN.
- 10/31/2000 Crew to location, conduct safety meeting, break circulation, circulate hole clean, mix and pump 38 sxs class "B" cmt (44.84 cu. ft.) flush w/ 14 bbls. Good circulation throughout job, POOH w/ 26 jts. Secure well, SDFN.
- 11/1/2000 Crew to location, conduct safety meeting, TIH w/ 2 7/8" tbg., tag TOC @ 2522' (perfs. @ 2760'-62') POOH w/ tbg. Prepare to free point, cut and pull csg.
- 11/2/2000 Crew to location, conduct safety meeting, MIRU wireline truck, free point and cut csg. @ 1445', rig dn. wireline truck, POOH and lay dn. 5 1/2" csg., PU and TIH w/ 2 7/8" tbg. to 1873' (top of Gallup 1766') Break circulation, circulate hole clean, mix and pump 132 sxs class "B" cmt. (155 cu. ft.) flush to 1200', POOH w/ tbg., secure well, SDFN.
- 11/3/2000 Crew to location, conduct safety meeting, PU and TIH w/ 2 7/8" tbg., tag TOC @ 1085', POH to 140' (8 5/8" shoe @ 65') circulate hole clean, mix and pump 73 sxs. class "B" cmt. (86.66 cu. ft.) w/ good slurry to pit, POOH w/ tbg., top off 8 5/8" csg., hole stable, rig dn, move all equipment, install P & A marker, clean location, final report.