



OIL CONSERVATION COMMISSION

STATE OF NEW MEXICO
1000 RIO BRAZOS RD. - AZTEC

87410

I. R. TRUJILLO
CHAIRMAN

LAND COMMISSIONER
PHIL R. LUCERO
MEMBER

STATE GEOLOGIST
A. L. PORTER, JR.
SECRETARY - DIRECTOR

September 16, 1975

Davis Oil Company
1230 Denver Club Building
Denver, Colorado 80202

Re: Davis Oil Company
Chacra Mesa #1
B 18-19N-6W

Gentlemen:

We have been holding a subsequent report of abandonment for the subject well since December 30, 1971.

We cannot approve the plugging until the dry hole marker is cemented in the well.

A recent field inspection found the marker pipe standing at about a 45° angle.

A second notice was mailed to you on September 6, 1973, that the marker was not cemented.

Please cause this situation to be corrected before winter weather arrives.

If there are questions please contact us.

Yours very truly,

A. R. Kendrick
Engineer, District #3

cc: OCC, Santa Fe, N.M.

Q K

10-29-75

O.G.

ARK/bk