

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NCC-C-14-20-4305	
2. NAME OF OPERATOR Basin Fuels Inc., Formerly Burr & Cooley		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo Allotted	
3. ADDRESS OF OPERATOR 152 Petroleum Center Bldg., Farmington, New Mexico		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2200' FNL & 1650' FWL		8. FARM OR LEASE NAME BSK Edna	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DE, RT, GR, etc.)		10. FIELD AND POOL, OR WILDCAT Lone Pine Dakota "D"	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 8, T17N, R8W	
		12. COUNTY OR PARISH McKinley	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	



(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Plug and Abandon Procedure

Note: Dakota Zone abandoned via sundry notice dated 5-22-74.

MIRU casing pulling unit. Spot 35 sk. cement plug over Hospah perf's. 1807-11. Shoot off csg. at estimated 1100 ft. Spot 35 sk. plug in stub (100 ft. above and below). Spot 10 sks. cement plug at surface. Install dry hole marker. Clean up location.



18. I hereby certify that the foregoing is true and correct

SIGNED Jack D. Cook TITLE Agent DATE 9-19-74

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: