

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. X-1883	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Dry hole		7. Unit Agreement Name
2. Name of Operator Burwinkle, Scanlon & Husky Energy Inc.		8. Farm or Lease Name Jaco
3. Address of Operator Box 388, Aztec, New Mexico		9. Well No. 54
4. Location of Well UNIT LETTER D 660 FEET FROM THE North LINE AND 660 FEET FROM West LINE, SECTION 28 TOWNSHIP 20N RANGE 9W NMPM.		10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 6500 GR		12. County McKinley

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>
REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>	
ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>	


17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well plugged and abandoned as follows:

6-1/8" hole 18 sx per 100'
100' plug - 3600 - 3700
100' plug - 2550 - 2650
100' plug - 400 - 500

5 sx plug at surface - set marker

cleaned and leveled location.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

BURWINKLE, SCANLON & HUSKY ENERGY INC.

SIGNED *Noel Reguerra* TITLE **Agent** DATE **April 27, 1972**

APPROVED BY *Ernest C. Carter* TITLE **SUPERVISOR DIST. #3** DATE **AUG 15 1972**
 CONDITIONS OF APPROVAL, IF ANY:

NEW MEXICO OIL CONSERVATION COMMISSION
1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO

Burwinle, Scanlan & Husky Energy Inc
Po Box 1 Reynolds
Box 388, Aztec, N.M

Re: Plugging Reports

Gentlemen:

Form C-103, Notice of Intention to Plug, your

Jaco

54

D-28-20N-9W

Lease

Well No.

5-1-72

was approved

Your

Unit

S-T-R

subsequent notice of plugging cannot be approved until a commission representative has made an inspection of the location to see:

- (1) all pits have been filled and leveled;
- (2) a steel marker, 4" in diameter and approximately 4' above mean ground level, must be set in concrete, this marker must have the quarter-quarter section or unit designation, section, township and range numbers, which shall be permanently stenciled or welded on the marker;
- (3) the location shall be cleared and cleaned of all junk;
- (4) the dead man wires must be cut.

The above are the minimum requirements.

Please notify us by filling in the blank form below when this work has been done so that our representative will not have to make more than one trip to the location.

OIL CONSERVATION COMMISSION

By

Emory C. Gandy

Fill in below and return:

Lease

Well No.

Unit

S-T-R

is ready for your inspection and

approval.

Operator

Name and title

Final location marker set