UNITED STATES DEPARTMENT OF THE INTERIOR	5. LEASE NM-24620 -
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas cother well well other	Lone Pine Dakota D Unit 9. WELL NO.
2. NAME OF OPERATOR	29
Tenneco Oil Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Lone Pine Dakota D
720 S. Colo. Blvd., Denver, CO 80222 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA
below.)	Sec. 8; T17N; R8W
AT SURFACE: 2310'-FNL, 990'FWL, Unit E	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH:	McKinley New MExico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	44. ATT NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	\7033'KB
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: STEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL SHOOT OR ACIDIZE	
FRACTURE TREAT SHOOT OR ACIDIZE TO THE TREAT SHOOT OR ACIDIZE	
SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE MULTIPLE TREAT GUERN GUERN	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	URVEY change on Form 9-330.) -
CHANGE ZONES	- MARINE CENSA (
MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)	TO LANCOR
(Other)	O CONTRACTOR OF THE PARTY OF TH
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di 	e all pertinent details, and give pertinent dates
measured and true vertical depths for all markers and zones pertinen	it to this work.)*
12/13/79	· [] [[살병[원호] 및
Tenneco Oil Company has plugged and abandoned following procedure:	the above well using the
4 14 2 2 2 2	plugs w/CL B cmt. 2% CACL2 @
er ead onto:	owing depths: 6505-400' 7348
3. Fill hole w/produced water	1700 = 1600 (25 sxs)
4. POOH w/tubing	100'-Surface (25 sxs)
5. Squeeze Dakota perforations 7. RDMOPU @ 2802'-2807' w/50 sxs CL B 8. Install	P&A marker
	rade and restore location per
_ '	quirements. Add and Adda
	그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그

Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct Admin. SupervisorDATE SIGNED TITLE DATE

Approved as to plugging of the well bore. Liability under bond is retained

until surface restoration is completed.