

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P & A	7. Unit Agreement Name
2. Name of Operator Northern Minerals, Inc.,	8. Farm or Lease Name Fernandez
3. Address of Operator P. O. Box 2182, Santa Fe, New Mexico 87501	9. Well No. 9
4. Location of Well UNIT LETTER G , 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 31 TOWNSHIP 16N RANGE 8W NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 6996' G. L.	12. County McKinley

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:


PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was plugged and abandoned on June 10, 1973, and was turned over to Landowner for conversion to water well from the Massive Gallup. Plugs were set at the following depths in accordance with instructions from Mr. E. C. Arnold, Supervisor of the New Mexico Oil Conservation Commission:

100' plug across the top Dakota "D", 2200 to 2300
100' plug across top of Lower Mancos Shale, 1350 to 145
Cap on top of Surface Pipe.

Hole was left filled with mud. Affidavit of Responsibility
Conversion to Water well will be executed by Operator and Landowner and filed with the Commission.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Lloyd Davidson TITLE President DATE 6-16-73
APPROVED BY Ernest C. Arnold TITLE SUPERVISOR DIST. #3 DATE NOV 1 1973
CONDITIONS OF APPROVAL, IF ANY:

NEW MEXICO OIL CONSERVATION COMMISSION
1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO

100. Therman Minerals Inc
PO Box 2182
Santa Fe, New Mex 87501

Re: Plugging Reports

Gentlemen:

Form C-103, Notice of Intention to Plug, your Fernandez 9
Lease Well No.

G. 31-16 N- 8 W was approved 6-18-73. Your
Unit S-T-R

subsequent notice of plugging cannot be approved until a commission representa-
tive has made an inspection of the location to see:

- (1) all pits have been filled and leveled;
- (2) a steel marker, 4" in diameter and approximately 4' above mean ground level, must be set in concrete, this marker must have the quarter-quarter section or unit designation, section, township and range numbers, which shall be permanently stenciled or welded on the marker;
- (3) the location shall be cleared and cleaned of all junk;
- (4) the dead man wires must be cut.

The above are the minimum requirements.

Please notify us by filling in the blank form below when this work has been done so that our representative will not have to make more than one trip to the location.

OIL CONSERVATION COMMISSION

By Fernandez

Fill in below and return:

Lease Well No. Unit S-T-R is ready for your inspection and
approval.

loc imp 14-1-73
OK

Operator

Name and title