

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> P & A		7. Unit Agreement Name
2. Name of Operator Northern Minerals, Inc.		8. Farm or Lease Name SFPRR
3. Address of Operator P. O. Box 2182, Santa Fe, New Mexico 87501		9. Well No. 6
4. Location of Well UNIT LETTER <u>G</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>29</u> TOWNSHIP <u>16N</u> RANGE <u>6W</u> NMPM.		10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 6428' G. L.		12. County McKinley

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:


PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was plugged and abandoned on July 28, 1973. Cement plugs were set at the following intervals:

50' plug across top of Entrada sand - 3,016' to 3,066'
100' plug across Dakota "D" - 1800' to 1900'
100 sacks cement above Gallup, 812'
5 sacks in top of surface casing

A dry hole marker will be erected, the pits filled and the location restored.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Lloyd Davidson</u>	TITLE <u>President</u>	DATE <u>8-15-73</u>
APPROVED BY <u>Ernest Cuneo</u>	TITLE <u>SUPERVISOR DIST. #5</u>	DATE <u>8-15-73</u>
CONDITIONS OF APPROVAL, IF ANY:		