

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P & A	7. Unit Agreement Name
2. Name of Operator Northern Minerals, Inc.	8. Farm or Lease Name SFPRR
3. Address of Operator P. O. Box 2182, Santa Fe, New Mexico 87501	9. Well No. 5
4. Location of Well UNIT LETTER M , 660 FEET FROM THE South LINE AND 775 FEET FROM THE West LINE, SECTION 22 TOWNSHIP 15N RANGE 6W NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 6647'	12. County McKinley

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Landowner decided not to complete this well as a water well. Efforts have been, and are now being, made to plug this well. The surface casing fell into the hole. Water from the well caused a pool around the well. It has been impossible to get a rig over the hole. In December, 1974, the ground just to the East of the well was built up with a bulldozer so that a rig can get over the well. As soon as weather permits and a rig can be obtained, this well will be plugged and abandoned in accordance with the Commission's regulations.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Lloyd Davidson TITLE President DATE 1-10-75

APPROVED BY [Signature] TITLE SUPERVISOR DIST. #3 DATE 1-14-75

CONDITIONS OF APPROVAL, IF ANY: