

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>P & A</u>	7. Unit Agreement Name
2. Name of Operator <u>Northern Minerals, Inc.</u>	8. Farm or Lease Name <u>SFPRR</u>
3. Address of Operator <u>P. O. Box 2182, Santa Fe, New Mexico 87501</u>	9. Well No. <u>9</u>
4. Location of Well UNIT LETTER <u>H</u> <u>1650</u> FEET FROM THE <u>North</u> LINE AND <u>335</u> FEET FROM THE <u>East</u> LINE, SECTION <u>31</u> TOWNSHIP <u>16N</u> RANGE <u>6W</u> NMPM.	10. Field and Pool, or Wildcat <u>Wildcat</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>6521 G. L.</u>	12. County <u>McKinley</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was plugged and abandoned on 12-23-73. Total Depth was 862'. Cement plugs were set as follows:

100' plug on bottom
50' plug in surface

All pits have been filled and leveled; a steel marker, 4" in diameter and approximately 4' above mean ground level, has been set in concrete, the quarter-quarter section, township and range has been welded on the marker; location has been cleared of all junk; dead man wires have been cut.

The location is now ready for your inspection.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Lloyd Davidson</u>	TITLE <u>President</u>	DATE <u>5-22-74</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR DIST. 3</u>	DATE <u>5-24-74</u>
CONDITIONS OF APPROVAL, IF ANY: <u>See Perry 5-74</u>		