

Will file

TESORO PETROLEUM CORPORATION

Suite 2000 First of Denver Plaza Building

633 Seventeenth Street

DENVER, COLORADO 80202

Rocky Mountain District

(303) - 825-2000

March 2, 1977

Mr. A.R. Kendrick
Supervisor & Oil &
Gas Inspector
1000 Rio Brazos Road
Aztec, New Mexico 87410

Re: Hospah Dakota
Hanson #25

Dear Mr. Kendrick:

We recently received a copy of a report from the NMOGC which indicated the captioned well to be over produced. Since our letter of April 10, 1976, in which we requested continued operation of this well, the produced gas has been used for the operation of the several Tesoro leases in the Hospah field. At that time we discontinued outside sale of this gas and we have been able to reduce the over-production considerably and believe within a year the overproduced status will not exist.

We sincerely appreciate your working with us on this problem and again we request permission to continue the operation of the Hanson #25.

Very truly yours,

William F. Parks
William F. Parks
District Production Superintendent

WFP/dlf

cc: Joe Howard
Dave Collis

[Circular stamp: RECEIVED MARCH 10 1977]