

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	1
LAND OFFICE	1
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Fairfax Exploration Inc.	8. Farm or Lease Name Bullseye
3. Address of Operator 301-B Graceland S.E., Albuquerque, N.M. 87108	9. Well No. 2
4. Location of Well UNIT LETTER <u>N</u> <u>540</u> FEET FROM THE <u>South</u> LINE AND <u>1560</u> FEET FROM THE <u>West</u> LINE, SECTION <u>18</u> TOWNSHIP <u>16 N</u> RANGE <u>9 W</u> NMPM.	10. Field and Pool, or Wildcat Wildcat-Dakota
15. Elevation (Show whether DF, RT, GR, etc.) 7244 GR	12. County McKinley

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Temporary abandonment</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set GO Elite bridge plug @ 1960' (4 1/2" drillable.) Aug. 20, 1974.

Set Guiberson 4 1/2" cast iron plug @ 932'. (Note: While setting plug 2 3/8" tubing leaving 14 joints of tubing and plug setter in hole, will attempt to retrieve at a later date.) Aug. 25, 1974

Set valve and bull plugs on top of 4 1/2" casing at surface. Aug. 25, 1974

Placed appropriate sign stating that well is temporarily abandoned. Sept. 12, 1974

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE President DATE Sept. 13, 1974

APPROVED BY [Signature] TITLE SUPERVISOR DIST. #5 DATE SEP 24 1974

CONDITIONS OF APPROVAL, IF ANY: