

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	2
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
K-5128

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Saguaro Oil Company	8. Farm or Lease Name Moran State
3. Address of Operator P. O. Box 51, Farmington, New Mexico 87401	9. Well No. 1
4. Location of Well UNIT LETTER <u>A</u> , <u>990</u> FEET FROM THE <u>North</u> LINE AND <u>990</u> FEET FROM THE <u>East</u> LINE, SECTION <u>36</u> TOWNSHIP <u>18N</u> RANGE <u>9W</u> NMPM.	10. Field and Pool, or Wildcat Hospah Upper Sand
15. Elevation (Show whether DF, RT, GR, etc.) 7065 Grd.	12. County McKinley

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pulled rods and tubing spotting plugs as follows, with a state representative present:

- # 1 plug through tubing 1744-1644 with 12 sacks.
- # 2 plug through tubing 700-800 with 22 sacks.
- # 3 plug shot pipe @ 120 and cemented with 10 sacks.

Set top plug and dry hole marker and cleaned location.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John Cunningham TITLE Manager DATE 9/15/78  
APPROVED BY AK Kendrick TITLE SUPERVISOR DIST. #4 DATE 9-22-78  
CONDITIONS OF APPROVAL, IF ANY:

1. The first step is to identify the problem or question that needs to be answered. This involves understanding the context and the specific requirements of the task.

125

—

• 2000

1000

2

—

100

• Although we have been able to find no other studies that

2000