

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-7509

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Scooter

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Extension-Unnamed

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 18, T20N, R5W

12. COUNTY OR PARISH

McKinley

13. STATE

N. Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Basin Fuels, Inc.

3. ADDRESS OF OPERATOR

152 Petroleum Center Bldg., Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

660' FNL & 660' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6729' G.L.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

REPAIRING WELL

☐
☐
☐
☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other) Application to Drill.

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7-1-2-3-75: MIRUPU - Aztec Well Service - Run correlation collar and cement bond logs. Perf. point lookout 2795-98 w/2 jets/ft. Swab dry. Acidize w/250 gal. 15% MCA. Swab final rate 4 BWPH - no shows. Set CIBP @ 2700 ft. Perf. point lookout 2762-67 w/ 2 jets/ft. Swab test.

7-5-6-7-75: Perf. point lookout 2726-30 w/ 2 jets/ft. Acidize w/250 gal. 15% MCA. Swab test. Perf. 2692-2699 w/2 jets/ft. Swab test. Run tbgs. & rods.

7-10-75: Set test equipment - Testing well.



18. I hereby certify that the foregoing is true and correct

SIGNED

Jack D. Cook

TITLE Pet. Engineer

DATE 7-10-75

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side