

submitted in lieu of Form 3160-5

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Sundry Notices and Reports on Wells

1. Type of Well OIL	5. Lease Number NMNM-12201
2. Name of Operator NERDLIHC	6. If Indian, All. or Tribe Name
3. Address & Phone No. of Operator C/O NMOCD, 1000 Rio Brazos Road, Aztec, NM 87410	7. Unit Agreement Name
Location of Well, Footage, Sec., T, R, M 990' FNL and 330' FEL, Unit A, Section 24, T-16N, R-10W	8. Well Name & Number Mareline #5
	9. API Well No. 30-031-20513
	10. Field and Pool
	11. County & State McKinley County, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission	Type of Action
☐ Notice of Intent	☒ Abandonment
☒ Subsequent Report	☐ Recompletion
☐ Final Abandonment	☐ Plugging Back
	☐ Casing Repair
	☐ Altering Casing
	☐ Other -
	☐ Change of Plans
	☐ New Construction
	☐ Non-Routine Fracturing
	☐ Water Shut off
	☐ Conversion to Injection

13. Describe Proposed or Completed Operations

This well was plugged under NMOCD Contract #00-521-25-205 per attached work report.

14. I hereby certify that the foregoing is true and correct.

Signed William F. Clark Title Contractor Date 1/8/01
William F. Clark

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____
CONDITION OF APPROVAL, if any: _____

RECEIVED FOR RECORD

JAN 17 2001

BY gma DATE _____

Daily Report

A - PLUS WELL SERVICE

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211Rig No #1 Date Multiple
Well No Manuelia #5 Location A-24-16-10 Company Needline

FROM	TO	DESCRIPTION OF OPERATION
		<i>No tubing in well</i>
		<i>Oct 30, 2000 Wireline - Bounce Mountain NMWD</i> <i>Run 4 1/2" CIP to 1780' (Wrong string steel)</i>
		<i>Wed 11-1-00 R-O Wireline. T.H. & Set 4 1/2" Plug well R.O.P. @ 1,696'. POOH. R-D</i> <i>Wireline. Bruce Martin w/ NMWD on loc. R.W. & S.S.</i>
		<i>Mon 11-13-00 R-O CUD & PT #104. T.H. with coiled TBG & TAG CIP @ 1,696'. Load &</i> <i>circulate the hole clean with 15 BBLs water. Test CSG to 500' Hold</i> <i>5 min OK. Plug #1 mix & Pump 12 SKS cement, ^{15.5"} from 1,696' to TAC @ 1,538'.</i> <i>POOH with TBG to 983' Load the hole with 2 BBLs water. Plug #2 mix</i> <i>& Pump 20 SKS cement, ^{15.6"} from 983' to TAC @ 719'. POOH with TBG to</i> <i>500'. Circulate hole with 10 BBLs water. POOH. R-O equip. mal.</i> <i>Bruce Martin w/ NMWD on loc.</i>
		<i>Mon 11-20-00 T.H. with wireline & TAG TAC @ 722'. POOH. Henry Villaseca w/ NMWD on loc</i> <i>& OK'd TAG @ 722' & set to TOP off to 719'.</i>
		<i>Wed 12-6-00 Dig out & cut well head off. 7 5/8" CSG cement @ surf. T.H. with 1 1/4" coiled TBG</i> <i>to 165'. Load the hole with 1/2 BBL water. Plug #3 mix & Pump 32 SKS cement, ^{15.6"}</i> <i>from 165' with good cement. Returns out 4 1/2" CSG. POOH with TBG. Set marker</i> <i>& TOP off CSG with cement left in coiled TBG.</i> <i>Bruce Martin w/ NMWD on loc.</i>
		<i>Dec 2000 - Removed miscellaneous Junk.</i>

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment _____ Cement Retainers _____

Cementing ^{15.5"} P-#1-12 SKS ^{15.6"} P-#2-20 SKS ^{15.6"} P-#3-32 SKS & marker - *64 SKS*
Wireline *4 1/2" P.W. / CIP @ 1,696'* - *(bid - 90 SKS)*

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	<i>Bill Miller</i>			
Operator	<i>Bob Stuart</i>			
Helper	<i>Sam Stuart</i>			
Helper				
Helper				