

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

14-20-0603-9895

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo

7. UNIT AGREEMENT NAME

Lone Pine Dakota "D"

8. FARM OR LEASE NAME

9. WELL NO.

30

10. FIELD AND POOL, OR WILDCAT

Lone Pine Dakota "D"

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 18, T17N, R8W

12. COUNTY OR PARISH

McKinley

13. STATE

New Mexico

1. OIL ☐ GAS ☐ OTHER ☒ Dry Well

2. NAME OF OPERATOR

Tenneco Oil Company

3. ADDRESS OF OPERATOR

1860 Lincoln St., Suite 1200, Denver, Colorado 80203

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface

1365' FNL and 2621' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7008' GL

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

PULL OR ALTER CASING ☐

WATER SHUT-OFF ☐

REPAIRING WELL ☐

FRACTURE TREAT ☐

MULTIPLE COMPLETE ☐

FRACTURE TREATMENT ☐

ALTERING CASING ☐

SHOOT OR ACIDIZE ☐

ABANDON* ☐

SHOOTING OR ACIDIZING ☐

ABANDONMENT* ☒

REPAIR WELL ☐

CHANGE PLANS ☐

(Other) ☐

(Other) ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We have plugged and abandoned this well as follows:

1. MIRUPU
2. Pulled tbg. up to 2600' and squeezed Dakota perms with 50 sacks of cement. Top of cement @ 2689'.
3. Pulled tbg. up to 1650' and spotted 25 sack plug from 1650' - 1450'. Pulled tbg out of hole.
4. Ran free point. Shot 5-1/2" csg. off @ 669' and spotted 25 sack plug in and out of stub.
5. Spotted 35 sack plug @ 94' and a 15 sack plug from the surface to 30'. Installed dry hole marker, filled and leveled pits, cleaned area of all debris, and re-seeded.

RECEIVED

OCT 1 1976

18. I hereby certify that the foregoing is true and correct

SIGNED

A. A. Myer

TITLE Div. Production Manager

DATE

9-30-76

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: