

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Dry Well		5. LEASE DESIGNATION AND SERIAL NO. 14-20-0603-9895	
2. NAME OF OPERATOR Tenneco Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo	
3. ADDRESS OF OPERATOR 1860 Lincoln St., Suite 1200, Denver, Colorado 80203		7. UNIT AGREEMENT NAME Lone Pine Dakota "D"	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1365' FNL and 2621' FEL		8. FARM OR LEASE NAME	
14. PERMIT NO.		9. WELL NO. 30	
15. ELEVATIONS (Show whether DF, RT, CR, etc.) 7008' GL		10. FIELD AND POOL, OR WILDCAT Lone Pine Dakota "D"	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 18, T17N, R8W	
		12. COUNTY OR PARISH McKinley	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

We have plugged and abandoned this well as follows:

1. MIRUPU
2. Pulled tbq. up to 2600' and squeezed Dakota perms with 50 sacks of cement. Top of cement @ 2689'.
3. Pulled tbq. up to 1650' and spotted 25 sack plug from 1650' - 1450'. Pulled tbq out of hole.
4. Ran free point. Shot 5-1/2" csg. off @ 669' and spotted 25 sack plug in and out of stub.
5. Spotted 35 sack plug @ 94' and a 15 sack plug from the surface to 30'. Installed dry hole marker, filled and leveled pits, cleaned area of all debris, and re-seeded.



RECEIVED

OCT 1976

18. I hereby certify that the foregoing is true and correct

SIGNED P. T. McGrath

TITLE Div. Production Manager

DATE 9-30-76

(This space for Federal or State office use)

APPROVED APPROVED

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

P. T. McGRATH

DISTRICT ENGINEER

\*See Instructions on Reverse Side