

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NOO-C-14-20-5792

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo Allotted

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Navajo Allotted 25

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SEC. 25, T20N, R5W

12. COUNTY OR PARISH 13. STATE

McKinley New Mex.

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry Hole

2. NAME OF OPERATOR
Filon Exploration Corporation

3. ADDRESS OF OPERATOR c/o Minerals Management Inc.
501 Airport Dr., Suite 105, Farmington, New Mex. 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OK, etc.)
6633 GR- 6645 RT

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☒
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)


17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Operator proposes to abandon well as follows:

Spot 25 sacks (100') plug 3230'-3330' (across base 4 1/2").
Run freepoint, cut 4 1/2" casing and pull.
Spot 25 sacks (100') plug across top of casing stub.
Spot 65 sacks (150') plug 500'-650'.
Spot 25 sacks (50') plug 204'-254' (base surface casing).
Spot 10 sacks (30') plug at surface.

Erect dry hole marker. Verbal approval to Plug and Abandon
from Ed Schmidt to J. Arnold Snell, on 3/9/76.

CONFIDENTIAL



18. I hereby certify that the foregoing is true and correct

SIGNED

J. Arnold Snell

Area Manager

TITLE Minerals Management Inc DATE March 9, 1976

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

