

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LG-3702-1
7. Unit Agreement Name
8. Farm or Lease Name
9. Well No. Crown Point # 1
10. Field and Pool, or Wildcat WC
12. County McKinley

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator WTR OIL COMPANY
3. Address of Operator P.O. Drawer LL, Cortez, Colo 81321
4. Location of Well UNIT LETTER A 500 FEET FROM THE North LINE AND 450 FEET FROM THE East LINE, SECTION 16 TOWNSHIP 18N RANGE 12W NMPM.
15. Elevation (Show whether DF, RT, CR, etc.) 6422.98 GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:


REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Proposed to plug and abandon as follows:

Shoot 4½" Casing off @ 1800 and pull
Cement from 2390' - 2290' with 11 sks
1150' - 1350' with 50 sks
750' - 450' with 75 sks
100' - 0' with 50 sks

Set plug and abandon marker; clean up and reseed location.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>James P. Hooley</u>	TITLE <u>Co-operator</u>	DATE <u>2-13-81</u>
Original Signed by FRANK T. CHAVEZ	SUPERVISOR DISTRICT <u>3</u>	DATE <u>FEB 17 1981</u>
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		