

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Fairfax Exploration, Inc.	8. Farm or Lease Name Bullseye
3. Address of Operator 301-B GRaceland S.E., Albuquerque, N.M. 87108	9. Well No. 8
4. Location of Well UNIT LETTER D 330 FEET FROM THE North 990 THE West LINE, SECTION 18 19 TOWNSHIP 16 N RANGE 9 W NMPM.	10. Field and Pool, or Wildcat Marcelina Dakota
15. Elevation (Show whether DF, RT, GR, etc.) 7187 GR	12. County McKinley


16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
Per Letter from Frank T. Chavez			

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Spudded 6:00 P.M. Janaury 18, 1978.
- Drilled 12 3/4" hole to 61'.
- Set 60' of 10 3/4" surface casing, 40.5# per foot.
- Cemented with 30 sx Portland cement, circulated approx. 5-10 sx to surface.
Pressure tested 600# for 12 hours.
- Drilled 7 7/8" hole to 732'.
- Hole is now covered with steel cap. Mud standing approx. 500' below surface.
No stuck pipe left in hole.
- Intend to plug as follows:
25 sx on bottom.
25 sx at 350'.
10 sx at 60'.
10 sx at surface.
Or as directed by NMOCC.

Will plug hole as soon as pulling unit is available to run tubing for spotting cement plugs.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Frank T. Chavez TITLE President DATE March 20, 1980

PROVED BY Original Signed by FRANK T. CHAVEZ TITLE SUPERVISOR DISTRICT # 3 DATE MAR 28 1980

INDICATIONS OF APPROVAL, IF ANY:
7-12-80 11:24 AM before commencing operations so that we may search witness