			file Co	*	
Form 9-331 (May 1963)	DEPARTMEN	ITED STATES NT OF THE INTERIOR (Other instructions verse side) LOGICAL SURVEY	CATE* On re 5. LEASE DESIGNATION A		
(Do not use the	JNDRY NOTICES	S AND REPORTS ON WELLS of drill or to deepen or plug back to a different reservoir. N FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE	OR TRIBE NAM	
1. OIL GAS			7. UNIT AGREEMENT NAM	í R	
2. NAME OF OPERATOR		Enduted Eno Prad Sers	8. FARM OR LEASE NAM		
3. ADDRESS OF OPERA	ATOR P.O. DOK	70	9. WELL NO.	<u> </u>	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*			10. FIELD AND POOL, OR	10. FIELD AND POOL, OR WILDCAT Wildcat 11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA	
See also space 17 below.) At surface 210 Fil. 230 Fil					
		SURVEY OR AREA			
			Sec. 35, 120		
14. PERMIT NO.	15	5. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH	New Head	
16.	Check Appro	priate Box To Indicate Nature of Notice, Report	t, or Other Data		
	NOTICE OF INTENTION		SUBSEQUENT REPORT OF:		
TEST WATER SHU	T-OFF PULL	OR ALTER CASING WATER SHUT-OFF	REPAIRING W	ELL	
FRACTURE TREAT	· [TIPLE COMPLETE FRACTURE TREATMENT			
SHOOT OR ACIDIZE REPAIR WELL		DON* SHOOTING OR ACIDIZE (Other)	NG ABANDONMEN		
(Other)	L	(Note: Report	results of multiple completion of Recompletion Report and Log for	on Well m.)	
		; and abandon by placement of cemer ming intervals: 325 - TD 2450	nt plugs		
	Plug #2	770 - 920			
	Plug#3				
	-	175 - 275			
	Plug #4	0 - Surface, install steel marker, I instructions obtained by phone i		3 ,	
	Plug #4 as per verbe on 5-5-1979	0 - Surface, install steel marker, I instructions obtained by phone i at 4:15 P.M.		s. E ()	
James	Plug #4 as per verba on 5-5-1979 hange L. Ku	0 - Surface, install steel marker, il instructions obtained by phone is at 4:15 P.M.	PEGEIV	E	
James	Plug #4 as per verba on 5-5-1979 hange L. Ku	0 - Surface, install steel marker, I instructions obtained by phone i at 4:15 P.M.	rom 2d Schmidt, USG	E (1)	
from [8. I hereby certify to	Plug #4 as per verbe on 5-5-1979 L. Lu Luginee that the ionegoing is true	0 - Surface, install steel marker, I instructions obtained by phone is at 4:15 P.M. To Level Level Level e and correct	DEGELV S. CLAUGH SA GRANGE COL	E D	
from 18. I hereby certify to SIGNED Origin.	Plug #4 as per verbe on 5-5-1979 L. Lu Luginee that the torageing is true and Signed By:	O - Surface, install steel marker, I instructions obtained by phone is at 4:15 P.N. To Levice Levice Agent TITLE	DECEIV	E D	
from 18. I hereby certify to SIGNED Origin.	Plug #4 as per verbe on 5-5-1979 L. Lu Luginee that the ionegoing is true	O - Surface, install steel marker, I instructions obtained by phone is at 4:15 P.N. To Levice Levice Agent TITLE	DEGELV SCHOOL SECTION COLUMNS 5-6-1	E D	