UNITED STATES DEPARTMENT OF THE INTERIOR

UNITED STATES	E LEACE TO 3 P. D.
	I D. LEMOE . Ye
DEPARTMENT OF THE INTERIOR	
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	Signal Si
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME 7. 8 8 8
	The state of the s
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME 4 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
1. oil 😡 gas 🗍	8. FARM OR LEASE NAME 를 드를 하다.
well well other	
2. NAME OF OPERATOR	9. WELL NO. The state of the st
BASIN FUELS, LTD.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR 87401	FRANCISCAN LAKE- MESA VERDE
Suite 300, 300 W. Arrington, Farmington, NM	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	
below.)	AREA PROBLEM SEC. 18, T20N, R5W S SEC.
AT SURFACE: 1980' FSL and 2310' FEL	12. COUNTY OR PARISH 13. STATE 2
AT TOP PROD. INTERVAL: Same	McKinley New Mexico
AT TOTAL DEPTH: Same	14. API NO. 특용성을 표 호텔 등
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	6746 Ground () [
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF 🗌	to got of
FRACTURE TREAT	6 4 4 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone change on Form 9-330.)
MULTIPLE COMPLETE	change on Form 9-330.) Problem on Service Problem on the Problem of the Problem o
CHANGE ZONES	arejiniy pitenego b pitenego b pitenego b pitenego pal basala pal basala pal basala pal basala pal basala pal basala
ABANDON* ☐ 🗓	그 그 그 아이는 동합식회 사람이 활성 존형 사람이
(other)	
	<u> </u>
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di 	e all pertinent details, and give pertinent dates, irectionally drilled give subsurface locations and
measured and true vertical depths for all markers and zones pertinen	t to this work.)*
Drill 6 3/4" hole to TD 2780'. Open hole logs	
be non-commercial. Plugged and abandoned well	as follows: [] La
Plug #1 30 sacks class "B" cement	2655-2755' 8 1 3 1 3 1 3 1 3 1 3 1 3 1 3 1 3 1 3 1
Plug #2 30 sacks class "B" cement	그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그
Plug #3 30 sacks class "B" cement	
Plug #4 35 sacks class "B" cement	20 - 2767 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
11dg #4 55 Sacks Class D Coment	LESSE LEVEL
Well Plugged and abandoned 5:30 PM, 04/23/79.	5 ぎらすばい ニーミシンカラ 一
Fenced pits. Will restore location to BIA and	11969 enecificationed to Hotelina
as practical.	obob specificational an acquiting
ub prudoudur.	មម្រង់គ្រឹង ម៉ូម៉ូម៉ូម៉ូម៉ូម៉ូម៉ូម៉ូម៉ូម៉ូម៉ូម៉ូម៉ូម
	· jaine a Expendent
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	승행문항의 등을 결정했습니다.
AGENT AGENT	April 25, 1979
JACK D. COOK	DATE
(This space for Federal or State offi	ce use)
	ACI HIGH SEED
APPROVED BY TITLE TOTALL	-/KILLIYED \
	MAY 11979
	IIIIII OF STATE OF ST
*See Instructions on Reverse S	oil con. com.
	DIST. 3