

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name Marcelina	
8. Farm or Lease Name Bullseye	
9. Well No. 9	
10. Field and Pool, or Wildcat Hospah	
12. County McKinley	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Capital Oil & Gas Corporation for Fairfax Expl. Inc.
3. Address of Operator P. O. Box 1038 Kilgore, Texas 75662	4. Location of Well UNIT LETTER 0, 330 FEET FROM THE South LINE AND 1650 FEET FROM THE East LINE, SECTION 18, TOWNSHIP 16N, RANGE 9W, NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 7186 GL	16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

PLUG AND ABANDON	<input checked="" type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input type="checkbox"/>
CASING TEST AND CEMENT JOBS	<input type="checkbox"/>	OTHER	<input type="checkbox"/>


17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pump 20 sx at perf - (168' cement - Top of plug 740')

Pump 10 sx at 120' - (Top of plug at 36')

Put 5 sx at surface and pipe marker. (Top of plug at surface)

George Operator from Fairfax



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>Harry Blanks</i>	TITLE <i>Rep</i>	DATE <i>4-27-81</i>
APPROVED BY <i>Original Signed by FRANK T. CHAVEZ</i>	TITLE <i>SUPERVISOR DISTRICT # 3</i>	DATE <i>MAY 4 1981</i>
CONDITIONS OF APPROVAL, IF ANY:		