

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Dry Hole</b>	7. Unit Agreement Name
2. Name of Operator <b>RIO COLORADO OIL &amp; GAS, INC.</b>	8. Farm or Lease Name <b>Santa Fe Pacific #8-19</b>
3. Address of Operator <b>1546 Cole Boulevard, Golden, CO 80401</b>	9. Well No. <b>#2</b>
4. Location of Well UNIT LETTER <b>H</b> , <b>2310</b> FEET FROM THE <b>North</b> LINE AND <b>990'</b> FEET FROM THE <b>East</b> LINE, SECTION <b>19</b> TOWNSHIP <b>17N</b> RANGE <b>9W</b> NMPM.	10. Field and Pool, or Wildcat <b>Wildcat</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>7061' G.L., 7065' K.B.</b>	12. County <b>McKinley</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Verbal permission was obtained from M. L. Kendrick of the New Mexico Oil & Gas Conservation Commission to plug and abandon the well as follows:

## Depth of Plug

## Sacks of Cement

2750'-2600'

28 Sks.

2500'-2400'

18 Sks.

1600'-1500'

18 Sks.

500'- 400'

18 Sks.

160'- 100'

18 Sks.

Surface w/Marker

10 Sks.



Well was plugged and abandoned 12/11/79 according to the above plugging program.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Petroleum Engineer DATE 12/15/79

Original Signed by CHARLES GHOLSON

DEPUTY OIL & GAS INSPECTOR, DIST. #3

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE SEP 9 1980

CONDITIONS OF APPROVAL, IF ANY: