

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name White Mesa	
8. Farm or Lease Name Lloyd Davidson SFPRR	
9. Well No. #1	
Wildcat Entrada	
10. Field and Pool, or Wildcat	
12. County McKinley	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" FORM C-101 FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator Capital Oil & Gas Corporation
3. Address of Operator P. O. Box 2130 Kilgore, Texas 75662
4. Location of Well UNIT LETTER <u>P</u> <u>1230</u> FEET FROM THE <u>East</u> LINE AND <u>960</u> FEET FROM THE <u>South</u> LINE, SECTION <u>29</u> TOWNSHIP <u>16N</u> RANGE <u>6W</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Will leave all 4½" casing. 0 - 3058'
- Set plug #1 at 2900'. 10 sks - 125' (between Entrada and Dokata)
- Set plug #2 at 1500'. 100 sks - 125' (between Dokata and Gallup)
- Set plug #3 at 900'. 10 sks - 125' (across Gallup)
- Set plug #4 and perf. at 60' - pump 10 sks plug.
- Weld on cap and set identification marker.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Harry Blumberg</u>	TITLE <u>Representative</u>	DATE <u>Sept. 16, 1982</u>
Original Signed by CHARLES GHOLSON		
APPROVED BY _____	TITLE <u>DEPUTY OIL & GAS INSPECTOR, DIST. #3</u>	DATE <u>SEP 15 1983</u>
CONDITIONS OF APPROVAL, IF ANY:		