



STATE OF NEW MEXICO  
**ENERGY AND MINERALS DEPARTMENT**  
OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE

GARREY CARRUTHERS  
GOVERNOR

1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO 87410  
(505) 334-5173

February 20, 1987

Mr. Bob Darben  
Tesoro Petroleum Corp.  
Star Route 2  
Cuba, NM 87013

Dear Bob:

Listed below are 6 of your injection wells which are exceeding pressure limitations.

Hanson #28 reported pressure 324 limit 315  
Hospah Sand Unit #87 reported pressure 392 limit 307--  
Hospah Sand Unit #91 reported pressure 316 limit 300  
Hospah Sand Unit #93 reported pressure 356 limit 300  
SFRR #10 reported pressure 319 limit 315  
SFRR #25 reported pressure 322 limit 315

In order to comply with the order authorizing injection, you are directed to cut back injection until you are in compliance.

Yours truly,

Charles Gholson  
Deputy Oil & Gas Inspector

CG/dj

cc: Well Files  
Operator File  
UIC Files  
Prentiss Childs