



STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT  
OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE

TONEY ANAYA  
GOVERNOR

1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO 87410  
(505) 334-6178

July 18, 1983

Mr. Dave Parks  
Tesoro Petroleum Corp.  
Suite 2000 First-of-Denver Bldg.  
633 17th Street  
Denver, CO 80202

Re: Hospah Sand Unit #49      A-1-17N-9W  
Hospah Sand Unit #92      O-36-18N-9W

Dear Dave:

NMOCD monthly production reports (form C-115) show the referenced wells are being injected into at pressures exceeding the pressure limits. The #49 at 640 PSI with a limit of 320 PSI and the #92 at 423 PSI with a limit of 300 PSI. Some type of remedial action must be taken. You may wish to change your injection pattern or you may wish to apply with the Division Director for pressure limit increases. Five more of your wells are slightly over their limits. You should be able to keep these within limits by slightly decreasing the flow to them.

If you have any questions, please call.

Yours truly,

Charles Gholson  
Deputy Oil & Gas Inspector

CG/ca

cc: Dick Stamets  
Prentiss Childs  
Judith Montoya, Injection Control Coordinator, Santa Fe  
Reading file  
✓ Well file  
Dave Collis, Tesoro Petroleum Corp., Farmington