Form 3160-5

LINITED STATES

FORM APPROVED			
Budget Bureau No. 1004-0135			
Expires: March 31, 1993			

Conversion to Injection

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

Dispose Water

une 1990)	DEPARTMENT OF THE		Budget Bureau No. 1004-0135 Expires: March 31, 1993
1	BUREAU OF LAND MA	NAGEMENT	RECE Pesignation and Serial No.
Do not use this	SUNDRY NOTICES AND REF	PORTS ON WELLS epen or reentry to a different	8 M N. 12335 6. If Indian, Allonee or Tribe Name
	Use "APPLICATION FOR PERMIT	—" for such proposals	192 UCT -2 AM II: 36
	SUBMIT IN TRIP	LICATE	19 FARM NGTON, N.M.
I. Type of Well Oil Ga	• 🗀		8. Well Name and No.
Oil Ga Well We 2. Name of Operator	eli U Other		South Hospah Unit # 65
•	Oil & Gas Corp.	713-469-9664	9. API Well No.
3. Address and Telephon		715-405-5004	
	ow Place South Ste 250 Hou	uston, Texas 77070	10. Field and Pool, or Exploratory Area
4. Location of Well (For	otage, Sec., T., R., M., or Survey Description)	,	S Hospah Legel Land
1418'FNL	. & 2769'FEL Sec. 12-17N-9	W	11. County or Parish, State
			McKinley County, NM
CHEC	K APPROPRIATE BOX(s) TO INC	DICATE NATURE OF NOTIC	E, REPORT, OR OTHER DATA
TYPE C	OF SUBMISSION	TYPE (OF ACTION
X Notic	ce of Internal	Abandonment	Change of Plans
_		Recompletion	New Construction
☐ Subs	equent Repart 3 OCT Q 7 1992	Plugging Back	Non-Routine Fracturing
	551 , 35	Casing Repair	☐ Water Shut-Off

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Other ___

Altering Casing

Plug and abandon

Citation Oil & Gas Corp. request permission to plug and abandon this well by using the following procedure:

- TIH w/open-end 2 7/8" tbg to TD (1613 ft). Spot 66 sx Class 1. B cmt w/2% Cacl2, pull to +/- 1200 ft, circulate tbg clean. WOC 2 hrs.
- Tag TOC. Spot 9 ppg mud from TOC to +/- 575 ft. Pull tbg to 2. 575 ft. Pump 170 sx Class B neat (volume will fill csg and tbg to surface). LD tbg. Top off csg when 1 jt remains in hole. LD jt.
- Cut off casing and weld on plate with 4" x 4' marker post. 3. Clean location.

4. I hereby certify that the foregoing is true and correct Signed Show Eq. (1)	Title Production Regulato	ory Supv Date 9-29-92
(This space for Federal or State office use) Approved by Conditions of approval, if any:	Title	APRROVED 900/03/1992
itle 18 U.S.C. Section 1001, makes it a crime for any person knowingly representations as to any matter within its jurisdiction.	y and willfully to make to any department or ag	ency of the Maried Supplier Asil Achieved Introduient state